

Table 1
 2-10-15 DGA Photolog
 Martha Zoe Moore, et al v. Denbury Onshore, LLC
 Richland Parish, Louisiana

Photo ID	Image ID	Date	Latitude	Longitude	Direction	Description
1	IMG_0531	2/10/2015	32.41296	-91.56152	East	Low wetland area full of cattails
2	IMG_0532	2/10/2015	32.41296	-91.56152	Northeast	Low wetland area full of cattails
3	IMG_0533	2/10/2015	32.41296	-91.56152	North	Low wetland area full of cattails
4	IMG_0534	2/10/2015	32.41333	-91.56126	North	B-10 location
5	IMG_0535	2/10/2015	32.41333	-91.56126	West	Four wheeler
6	IMG_0536	2/10/2015	32.41452	-91.56145	North	B-39 location
7	IMG_0537	2/10/2015	32.41452	-91.56145	South	Looking south from B-39 location
8	IMG_0538	2/10/2015	32.41587	-91.56258	North	
9	IMG_0539	2/10/2015	32.41587	-91.56258	East	
10	IMG_0540	2/10/2015	32.41587	-91.56258	Southeast	
11	IMG_0541	2/10/2015	32.41653	-91.56312	Northeast	Looking at pond north of northwest fence line
12	IMG_0542	2/10/2015	32.41653	-91.56312	East	
13	IMG_0543	2/10/2015	32.41653	-91.56312	Southeast	
14	IMG_0544	2/10/2015	32.41655	-91.56168	North	Pond, taken from along new fence line
15	IMG_0545	2/10/2015	32.41655	-91.56168	Southeast	
16	IMG_0546	2/10/2015	32.41655	-91.56168	Southwest	
17	IMG_0547	2/10/2015	32.4165	-91.56137	South	Note large amount of standing water
18	IMG_0548	2/10/2015	32.4165	-91.56137	Southwest	Note large amount of standing water
19	IMG_0549	2/10/2015	32.41357	-91.5611	Northwest	Cork temp well location, Charles pushing hand probe
20	IMG_0550	2/10/2015	32.41357	-91.5611	North	Along pipeline row
21	IMG_0551	2/10/2015	32.41356	-91.56126	Northwest	M-SB-01 Arabic former well location. Arabic well location -50' from Cork
22	IMG_0552	2/10/2015	32.41301	-91.55932	West	Green flag marking boring location in foreground
23	IMG_0553	2/10/2015	32.41301	-91.55932	East	
24	IMG_0554	2/10/2015	32.41301	-91.55932	North	
25	IMG_0555	2/10/2015	32.41301	-91.55932	South	
26	IMG_0557	2/10/2015	32.41304	-91.55833	North	B-51
27	IMG_0558	2/10/2015	32.41328	-91.55746	Northeast	B-52, note deer stand in background
28	IMG_0559	2/10/2015	32.41328	-91.55746	Southwest	
29	IMG_0560	2/10/2015	32.41457	-91.55566	Northeast	Drainage from road over culvert
30	IMG_0561	2/10/2015	32.41457	-91.55566	Southwest	Drainage from road over culvert
31	IMG_0562	2/10/2015	32.41385	-91.55771	Northwest	B-53
32	IMG_0563	2/10/2015	32.41385	-91.55771	Southeast	
33	IMG_0564	2/10/2015	32.41482	-91.55888	East	Note drainage? ditch in foreground
34	IMG_0565	2/10/2015	32.41482	-91.55888	North	
35	IMG_0566	2/10/2015	32.41482	-91.55888	West	
36	IMG_0567	2/10/2015	32.41582	-91.56069	Northwest	B-46
37	IMG_0568	2/10/2015	32.41582	-91.56069	West	
38	IMG_0569	2/10/2015	32.41582	-91.56069	East	

Notes:

1) DGA - David G. Angle of Michael Pisani & Associates, Inc.