A A A A A A A A A A A A A A A A A A A

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

Date: Thursday, March 9, 2023 Time of Arrival: 11:15 AM Time of Departure: 1:15 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, K Lavergne, R Broussard, Tanner Construction, ERM

Weather Conditions (Temp/Wind Speed/Direction, etc.): 80 degrees, SW Winds 8 mph, Overcast

Any planned work for today: Check pressures and inspect bubbling locations

•	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL 11-16	Location 9 (Water location	CL-4	CL-5	Yellow Rock Wells	Flowlines
(location description):				side of Central Lake)	(Bubbling locations near bulkhead)	between PPG 2 and		(Central Lake bubbling site)	Two SWDs and One Production	(all brine and oil flowlines)
General Comments: ERM was on location collecting samples of the sheen seen by CES Carnes in Crystal Lake on 3/6. A sample was also being collected from a 700 ft. deep unregistered water well near the cabins on Crystal Lake.		The pad is dry so if	Pumping 238 GPM; Historic saltwater leaks noted on various connections, but are scheduled to be repaired post-sonar next week.		Only one location nearest the bulkhead was able to be seen due to wind		No Access	No Access	SN 110159 (SWD) tbg - 80, csg - 0; SN 109963 (SWD) tbg - 3, csg - 0; SN 209459 (Producer) tbg - 50, csg - 55	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	188.3	N/A	88.6	N/A	N/A	N/A				
Casing Pressure (if applicable)	190.9	N/A	451.8	N/A	N/A	N/A				
Bubbling?	No	No	No	Yes	Yes	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	Yes	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				