INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

 Date:
 Thursday, April 13, 2023
 Time of Arrival:
 8:30 AM
 Time of Departure:
 11:30 AM

Inspector Name(s): William [Billy] Carnes

Other personnel on site: Vance Hill [YellowRock] Randy Broussard [Westlake]

Weather Conditions (Temp/Wind Speed/Direction, etc.): Partly Cloudy 67 deg. NNE 5 mph Calm

Any planned work for today: MIPT Yellowrock S-4 swd Well, Checked Cavern pressures & Bubbling sites

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Site's 9 & 19	Yellowrock	Yellowrock		
(location description):				(near BW-22, west					
				side of Central			check tubing		1
				Lake)	Site's on the map	S-4 swd Well	pressures		
On the Boat ride today I observed that the Bubbling in the area of site's 5,17,18 & 21 was more intense than the last time I was in the boat. Also it looked like between site's 8 & 22 was a line of bubbling that was connecting these 2. The other bubbling site's looked about the same from previous inspections in Central Lake.				Bubbling here looked more intense than on the 4/10 inspection		Operator repaired Well & I witness the MIPT, placed a lockout tag on wing valve that stated that Operator is NOT to use Well for disposal.	S-40 psi tubing		
Photos taken? (save to F: drive)	no	no	no	no	no				
Tubing Pressure (if applicable)	179	n/a	101						
Casing Pressure (if applicable)	182	n/a	466						
Bubbling?	no	yes	yes	yes					
Sheen?	no	no	no	yes					
Oil?	no	no	no	yes					
Odor?	no	no	no	yes					
Any new remedial work?	no	no	no	no					
Any impact to vegetation?	no	no	no	no					
Any impact to wildlife?	no	no	no	no					