MENT OF MA	INSPECTION FORM OFFICE OF CONSERVATION							BW No 21	and a start of the	NOV I	
								K	CE PERC		
		INJECTION & MINING DIVISION								BW. No. 20 - Active - Strengt (3)	
		617 NORTH 3RD STREET								273560 A RANK AND AN AND AND AND AND AND AND AND AND	
OPEC OF CONSERVITOR	BATON ROUGE, LA 70802									Arr Hilling	
Location: Sulphur Mines Dome								BW No.2		THE REANOUT	
Date: Thursday, May 4, 2023	Time of Arrival:	9.0	0 AM	Time of Departure:	12.5	30 PM		CONTRACT OF	0		
Inspector Name(s): William [Billy] Carnes		5.0	07111		. 12		13.3	Beaching and an and a second second		Dod II	
	' ergne, Turner contrac	rt hands & Stan's Airh	ooat w/driver						Allertine Million (201) BW/ No. 2 & 2A		i l
Weather Conditions (Temp/Wind Speed/Dir	-	Clear Sunny 74* ES						MA Va	Nº CO		
	vern well pressures, B	,	•	Control Lako inchoo	tion riding in Air Boot			1 m 20	RW. No. 4	12-15 B	
Any planned work for today: Check Cav	vern weil pressures, B	ubbling site s, reliow	rock wen pressures a	& Central Lake Inspec	tion haing in Air Boat						"
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-9 & 19	CL-3	CL-4	CL-5, 17, 18,21, 22 CL-7,8,13,14		CL-24	1
(location description):				(near BW-22, west					(a		
				side of Central Lake)	See Bubbling points on Map	(Central Lake bubbling site)	(Central Lake bubbling site)	(Central Lake bubbling site)	(Central Lake bubbling site's)	(central Lake bubbling site)	
				Lancy		babbining site)	Subbining Site)	babbining site;	Subbining Site 57	N 30* 15' 12.55" W	. ' 93* 24' 45.
Westlake had Stan's Airboat on site today											
had Airboat mash the vegetation down to											
be able to Observe any other bubbling sites. On Inspection I observed 1 bubbling site got											
GPS reading & it's called CL-24 .											
				This site looks the		Access that area	Access that area	The bubbling		New Bubbling site	
				same as on my	19 has a small	with Airboat today	with Airboat today			found with the	
		Well pad is dry not			bubbling train & 9	and it still had	& it was very little	looked the same as	-	airboat. Text video	
	ок	able to see bubbling sites	Injecting 258 gpm	Bubbling with some Oil	anything today.	several bubbling trains around.	bubbling in that area.	the inspection done on 5/1.	today	to Seth Henderson I & M Div. BR	
Photos taken? (save to F: drive)	no	no	no	no	no	no	no	no	no	yes	1
Tubing Pressure (if applicable)	180)	90)							1
Casing Pressure (if applicable)	184	Ļ	448	3]
Bubbling?	no	no	yes	yes	yes	yes	yes	yes	no	yes]
Sheen?	no	no	no	yes	no	no	no	no	no	no	
Dil?	no	no	no	yes	no	no	no	no	no	no	
Odor?	no	no	no	yes	no	no	no	no	no	yes	
Any new remedial work?	no	no	no	no	no	no	no	no	no	no	
Any impact to vegetation?	no	no	no	no	no	no	no	no	no	no	
Any impact to wildlife?	no	no	no	no	no	no	no	no	no	no	