INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, September 25, 2023 Time of Arrival: 11:15 AM Time of Departure: 12:30 PM Inspector Name(s): Sarah Hitchcock Other personnel on site: J. Bradley, R. Broussard, K. Lavergne, Control Room Personnel, Airboat Captain (Stan's Airboats), Turner Industries Weather Conditions (Temp/Wind Speed/Direction, etc.): 82 Degrees, Clear, Wind S at 4 mph										
Any planned work for today: Check pressures/observe bubbling locations										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central Lake)	<b>CL 11-16</b> (east side of Central Lake)	Location 9 (Water location between PPG 2 and PPG 4)	Yellow Rock Wells Two SWDs and One Production	Cavern Well 2	Central Lake (Central Lake Bubbling Locations)	Flowlines (all brine and oil flowlines)
NOTES: Both access gates (Westlake and Boardwalk) were closed. Access to the facility is restricted.		Pad is dry; no bubbling	Inj rate is 314 gpm; Minor bubbling alongside casing	Oil contained by sorbent boom. Water is very low.	Minimal bubbling near bulkhead.	Area is dry. No bubbling.	SN 110159 (SWD) tbg - 180, csg - 0; SN 109963 (SWD) tbg - 0, csg - 85; SN 209459 (Producer) tbg - 35, csg - 65		Did not ride airboat, but spoke with the airboat driver and he said that he did not observe any changes from the previous week.	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	N/A	N/A	71.7	N/A	N/A	N/A		245		
Casing Pressure (if applicable)	177.3	N/A	433	N/A	N/A	N/A		336.1		
Bubbling?	No	No	Yes	Yes	Yes	No				
Sheen?	No	No	No	No	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	Yes	No	No				
Any new remedial work?	No	No	No	No	No	No	ļ			
Any impact to vegetation?	No	No	No	No	No	No	ļ			ļ
Any impact to wildlife?	No	No	No	No	No	No				