Any planned work for today: Check pressures/observe bubblin Inspection locations: Cavern 6X (location description): Image: Cavern 6X Photos taken? (save to F: drive) No Tubing Pressure (if applicable) N/A Casing Pressure (if applicable) 174.9 Bubbling? No No 1	70 Degrees, Raining ling locations Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	1			DV No. 4 Masser Av773a	
Inspection locations: Cavern 6X (location description): - Photos taken? (save to F: drive) No Tubing Pressure (if applicable) N/A Casing Pressure (if applicable) 174.9 Bubbling? No Sheen? No	-	Cavern Well 7B		CL 11-16					
Photos taken? (save to F: drive) No Tubing Pressure (if applicable) N/A Casing Pressure (if applicable) 174.9 Bubbling? No Sheen? No			(near BW-22, west side of Central Lake)		(Water location between PPG 2 and	Yellow Rock Wells Two SWDs and One Production		Central Lake (Central Lake Bubbling Locations)	Flowlines (all brine and oil flowlines)
Tubing Pressure (if applicable) N/A I Casing Pressure (if applicable) 174.9 I Bubbling? No No Sheen? No I	There is standing water on pad for the first time in months; three distinct bubbling locations noted.	Inj rate is 321.4 gpm; Minor bubbling alongside casing	Oil contained by sorbent boom. Water is almost to normal level.	Minimal bubbling near bulkhead.	observed. Appears to be less than before	- 180, csg - 0; SN 109963 (SWD) tbg - 0,		Did not ride airboat, but spoke with Richard (airboat captain) and he said Location 3 is more active than observed on recent trips. LDNR personnel will ride airboat on Monday, 10/3, to confirm findings.	
Casing Pressure (if applicable) 174.9 Bubbling? No Sheen? No	No	No	No	No	No				
Bubbling? No No No	N/A	78.4	N/A	N/A	N/A		245	ļ	
Sheen? No I	N/A	433.5	N/A	N/A	N/A		340.3		
	Yes	Yes	Yes	Yes	Yes				
Oil? No	No	No	No	No	No				
	No	No	Yes	No	No				
Odor? No I	No	No	No	No	No				
Any new remedial work? No I	No	No	No	No	No				
Any impact to vegetation? No I	L.,	No	No	No	No				
Any impact to wildlife? No I	No	No	No	No	No				