Weather Conditions (Temp/Wind Speed/D	ate: Monday, October 9, 2023 Time of Arrival: 10:45 AM Time of Departure: 12:35 PM spector Name(s): Sarah Hitchcock ther personnel on site: J. Bradley, R. Broussard, Control Room Personnel, Turner Industries, Airboat Captain (Stan's Airboats) reather Conditions (Temp/Wind Speed/Direction, etc.): 75 Degrees, Sunny, Wind SSW at 7 mp+										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL 11-16 (east side of Central Lake)	Location 9 (Water location between PPG 2 and PPG 4)	Yellow Rock Wells Two SWDs and One Production	Cavern Well 2	Central Lake (Central Lake Bubbling Locations)	Flowlines (all brine and oil flowlines)	
		Very little water on pad. Two bubbling locations noted.	.	Oil contained by sorbent boom. Boom has been recently replaced.	Minimal bubbling near bulkhead.	Minimal bubbling. Only two distinct bubbling locations noted.	SN 110159 (SWD) tbg - 180, csg - 0; SN 109963 (SWD) tbg - 5, csg - 85; SN 209459 (Producer) tbg - 35, csg - 70		Central Lake water has risen significantly due to recent rainfall. Location 3 was very active and had multiple bubbling areas. A film/sheen was also observed at Location 3.		
Photos taken? (save to F: drive)	No	No	No	No	No	No			Yes		
Tubing Pressure (if applicable)	N/A	N/A	78.7		N/A	N/A		247.8			
Casing Pressure (if applicable)	175	N/A	434.9		N/A	N/A		349.7			
Bubbling?	No	Yes	Yes	Yes	Yes	Yes			Yes		
Sheen? Oil?	No No	No No	No	No Yes	No No	No No			Yes		
Odor?	No	No	No	No	No	No			No		
Any new remedial work?	No	No	No	No	No	No			No		
Any impact to vegetation?	No	No	No	No	No	No			No		
Any impact to wildlife?	No	No	No	No	No	No			No		