Date: Monday, February 3, 2025 Time of Arrival: 10:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Kevin LaVergne [westlake] Vance Hill [Yellowrock] Image: Control of the personnel on site: Kevin LaVergne [westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 67* to 73* Cloudy SSW 7 mph Any planned work for today: Check Cavern Well pressures, bubbling site's & some of Yellowrock Well pressures Inspection locations: Cavern 6X Cavern Well 7A Cavern Well 7B CL-1 CL site's Cavern Well 2 Cavern Well 2 Cavern Well 2 Cavern Well 20 Ye	ellowrock
Other personnel on site: Kevin LaVergne [westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 67* to 73* Cloudy SSW 7 mph Any planned work for today: Check Cavern Well pressures, bubbling site's & some of Yellowrock Well pressures	ellowrock
Weather Conditions (Temp/Wind Speed/Direction, etc.): 67* to 73* Cloudy SSW 7 mph Any planned work for today: Check Cavern Well pressures, bubbling site's & some of Yellowrock Well pressures	ellowrock
	ellowrock
Inspection locations: Cavern 6X Cavern Well 7A Cavern Well 7B CL-1 CL site's Cavern Well 2 Cavern Well 2a Cavern Well 4 Cavern Well 20 Ye	ellowrock
Inspection locations: Cavern 6X Cavern Well 7A Cavern Well 7B CL-1 CL site's Cavern Well 2 Cavern Well 2a Cavern Well 4 Cavern Well 20 Ye	ellowrock
Sulphur mines dome (near BW-22, west side of Central Lake)	
Fluid on pad Injecting 561 GPM Still bubbling with bubbling site's No bubbling site's No bubbling site's No bubbling site's	1017 240 psi ubing 240 psi asing// #1012 40 si tubing 40 psi asing// S-7 60 psi ubing 0 psi asing// S-4 15 psi ubing 360 psi asing
Photos taken? (save to F: drive)	
Tubing Pressure (if applicable) 103 psi	
Casing Pressure (if applicable) 619 psi 417 psi 264 psi 0.50 psi 278 psi 448 psi	
Bubbling? yes yes	
Sheen? no yes long long long long long long long long	
Oil? no yes long long long long long long long long	
Odor? no yes long long long long long long long long	
Any new remedial work? no	
Any impact to vegetation? no	
Any impact to wildlife? no no Image: Constraint of the second	