UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 7

DATE: 08/19/2012

Well TD:		**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:	1	**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** X **SW**

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6AM **QUITTING TIME:** 6AM 8/20/2012

ACTIVITIES:

Held safety meeting.
Finished nippling up and repaired flowline.
Loaded out hammer and csg tools.
Rigged up flare stack.
Changed out mud mixing pump.
Picked up swivel and kelly.
Drilled rat hole and mouse hole.
Picked up kelly bushing.
Picked up 17.5" bit,bit sub, and 8" drill collar.
Waiting on cross - over sub (4 hrs. down time on rig)

ESTIMATED TOTAL COST - **DAILY:** $64,566.00 **COST TO DATE:** $396,596.43

REMARKS: # 1 --17.5" bit (serial # 6070191)

Responsible Care
Good Chemistry at Work