UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 40

DATE: 09/21/2012

Well TD:	3180	**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:	5	**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** | **SW** X

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6AM **QUITTING TIME:** 6AM 9/22/2012

ACTIVITIES:

Held safety meeting.
Pull out of hole to check BHA
(Bearing in mud motor was worn out)
Picked up new 6 1/8" bit and new 4 3/4" mud motor.
and going in hole to 3180'

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care® Good Chemistry at Work