UNITED DRILLING SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 25

DATE: 09/06/2012

Well TD:	1103	**Well TD Yesterday:**	863	**Footage Drilled:**	240
Bit No:	3	**WGT. on Bit (000's):**	15	**Rotary RPM:**	45
Pump SPM:	75	**Pump PSI:**	1293	**Pump GPM:**	235

Mud System:

Type: **FW** [ ] **SW** [x]

Viscosity	9.9
Mud Weight	36
PV	3
YP	15
GEL	2/9

Inclination Surveys

Depth	Angle
871	.62°
902	.62°
934	.09°
966	1.58°
998	2.64°
1029	3.61°
1125	8.71°

Csg Depths	GL	RKB
20"	352	366
16	593	609
10 3/4"	840	856

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6 a.m. **QUITTING TIME:** 6 a.m. 9/7/2012

ACTIVITIES:

Held safery meeting.
Held BOP's and well control drill (3 min.)
Rig up Greene's testing unit and tested hydril,bop's
and ckoke manifold. OK
Picked up directional tools,mud motor and BHA.
Tested MWD and mud motor. OK
Going in hole to 863'
Drig sliding and survey. f / 863' t / 1103'

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care
Good Chemistry at Work