UNITED DRILLING SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 28

DATE: 09/09/2012

Well TD:	2717	**Well TD Yesterday:**	2463	**Footage Drilled:**	254
Bit No:	3	**WGT. on Bit (000's):**	15--20	**Rotary RPM:**	212
Pump SPM:	180	**Pump PSI:**	2050	**Pump GPM:**	565

Mud System:

Type: **FW** [ ] **SW** [x]

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB
20"	352	366
16	593	609
10 3/4"	840	856

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6: a.m. **QUITTING TIME:** 6 a.m. 9/10/2012

ACTIVITIES:

Held safety meeting,while waiting on welder.
Repair stand pipe with welder .
Going in hole to 2463'
Drlg f /2463' t / 2717'
Mix and pump hi - vis pill and circulate hole clean.
Laid down 56 jts. D.P.
Retrieve mwd survey tool and laid down directional tools.
Rigged up wireline and logging well.

3 bit -- 9 7/8" bit drilled 1854' in 49.5 hrs.

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care® Good Chemistry at Work