UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 11

DATE: 08/23/2012

Well TD:	610	**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:		**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** X **SW**

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6AM **QUITTING TIME:** 6AM 8/24/2012

ACTIVITIES:

Held safety meeting.
Underreaming 17.5" hole to 22" f / 455' t / 610'
Pump high vis pill and circulate hole clean.
Pull out of hole with 22" Underreamer.Cut straps off bit
and laid down same.
Rig up Baker Atlas wireline and run caliper log f/ 368' t/ 610'
and rig down same.
Nipple down BOP'S.

1 22" U.R. drilled 242' in 20 hrs.

ESTIMATED TOTAL COST - **DAILY:** $67,614.30 **COST TO DATE:** $717,388.41

REMARKS:

Responsible Care® Good Chemistry at Work