UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 27

DATE: 09/08/2012

Well TD:	2463	**Well TD Yesterday:**	1863	**Footage Drilled:**	600
Bit No:	3	**WGT. on Bit (000's):**	10 --- 15	**Rotary RPM:**	214
Pump SPM:	160	**Pump PSI:**	1950	**Pump GPM:**	570

Mud System:

Type: **FW** [ ] **SW** [X]

Viscosity	41
Mud Weight	10.1
PV	8
YP	17
GEL	3/15

Inclination Surveys

Depth	Angle
1884	40.19°
1978	42.12°
2073	41.94°
2168	39.92°
2263	36.23°
2358	31.74°
2453	27.44°

Csg Depths	GL	RKB
20"	352	366
16	593	609
10 3/4"	840	856

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6:a.m. **QUITTING TIME:** 6:a.m. 9/9/2012

ACTIVITIES:

Held safety meeting
Drlg,sliding and surveys f / 1863 t / 1958'
Drill into gas pocket,cut mud wt. f / 10.0 ppg t / 9.7 ppg
Build mud wt up to 10 ppg and circulate gas out of well.OK
Drlg,sliding and surveys f / 1958 t / 2463'
Stand pipe leaking ,pull up into csg and waiting on welder. (2.5 Hrs.)

3 bit -- 9 7/8" bit drilled 1600' in 43.5 hrs.

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care® Good Chemistry at Work