UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 29

DATE: 09/10/2012

Well TD: 2717 | **Well TD Yesterday:** | **Footage Drilled:**

Bit No: | **WGT. on Bit (000's):** | **Rotary RPM:**

Pump SPM: | **Pump PSI:** | **Pump GPM:**

Mud System:

Type: **FW** | **SW** x

Viscosity	36
Mud Weight	10.2
PV	8
YP	15
GEL	3/16

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB
20"	352	366
16	593	609
10 3/4"	840	856

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6 AM **QUITTING TIME:** 6AM 9/11/2012

ACTIVITIES:

Held safety meeting.
Rigged down wireline.
Picked up 12.25" underreamer w/ 8.5" spiral stabilzer
and going in hole to 850'
Under reaming 856' t / 1513'

1 underreamer -- 12.25" drilled 657' in 20.5 hrs.

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care® Good Chemistry at Work