UNITED DRILLING SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 48

DATE: 09/29/2012

Well TD:		**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:		**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** **SW**

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6AM **QUITTING TIME:** 6PM 9/30/2012

ACTIVITIES:

Held safety meeting.
Made up x- over sub on drill pipe.
Picked up same and screwed into hanger.
Lowered hanger into wellhead.Open choke line to mud tank
and check for flow.Well was flowing (Ring gasket not holding)
Pulled hanger up and check ring gasket (ring gasket cut in two)
Install new gasket on hanger and going back in hole.
Landed hanger into wellhead,check for flow (OK)
Closed top rams and pump in 4" tubing to pump out pumpout plug. (OK)
Close well in with master valve

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS:

Responsible Care® Good Chemistry at Work