UNITED DRILL SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 4

DATE: 08/16/2012

Well TD:		**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:		**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** **SW**

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

Orientate Riceland Drlg. Crews.

OPERATIONS: **START TIME:** 6:00 a.m. **QUITTING TIME:** 6:00 p.m.

ACTIVITIES:

Held safety meeting with truck drivers and rig crews.
Continued to move rig on location.
Spotted mud tanks,crew quarters, and raise derrick.

ESTIMATED TOTAL COST - **DAILY:** $1,650.00 **COST TO DATE:** $263,017.50

REMARKS:

Responsible Care® Good Chemistry at Work