

Q T E G L I V E D

MAY 1 0 1969

J. M. MENEFEE

DEPARTMENT OF CONSERVATION P. O. BOX 44275 - CAPITOL STATION BATON ROUGE 70804

May 14, 1969

Inspection & Enforcement Division

LeaseJeanerette Lbr. & Shingle Co.FieldBayou PigeonParishIberiaDate of InspectionMay 8, 1969

win Ber

K & H Operating Co. 839 Bankers Mortgage Bldg. Houston, Texas 77002

Gentlemen:

Representatives of the Inspection and Enforcement Division surveyed the production facilities in the above mentioned field and noted the following items which are not in line with the regulations set forth in Statewide Order No. 29-B. For your convenience, we have indicated the particular Sections and Paragraphs involved.

- 1. There are no tank battery or well signs to properly identify the lease Section X., Paragraph E., Section II., Paragraph D.
- 2. There is no retaining wall or spill pans around the stock tanks to prevent the spillage that occurs in everyday operations from resulting in pollution Section VIII., Paragraph C-3, & C-1.

Our Agent reports that waste oil was evident beneath the pump and heater-treater platform at the time of this inspection. He also reports that waste from the heater-treater is periodically flushed to natural drainage where it causes pollution. The lease is not equipped

*K & H Operating Co. May 14, 1969 Page -2-

with a sump or disposal pit to which all waste could be drained and stored for proper disposal. Attached hereto is a copy of his color photograph showing some of the oil pollution outlined above.

Please advise this Department within ten days of your plans to place the facilities on this lease in compliance with our Conservation regulations.

Yours very truly,

J. M. MENEFEE, Commissioner Department of Conservation

Ву

Fred Kring, J

Inspection and Enforcement Division

dwr

cc: Mr. R. H. Parro, Dist. Mgr. Houma, La.