

**From:** [Joe Ball](#)  
**To:** [Christen Willis](#)  
**Subject:** 12-29-12 Report  
**Date:** Wednesday, January 02, 2013 8:02:34 AM

---

**Sent:** Saturday, December 29, 2012 10:54 AM  
**Subject:** 12-29-12 Report

Oxy-Geismer #3-A Well shut-in, No tubing in well, Csg pressure 663 psi, all Cumulative totals are still the same as yesterday, 12-28-12 --TX Brine vent well #1 is flowing with a .79 psig tubing pressure and a flow rate of 23.2 mcf/day, Cumulative total Gas out 1,975.56 mcf --TX Brine Vent Well #2 is shut-in with a tubing pressure of 50 psi. -- No work is being done in or around the sinkhole today --The OG Water Well #3 was locked-out -- The TBC #1 was shut-in with a tubing pressure of 49 psig and a casing pressure of 36 psig -- The TBC #2 Shut-in with a tubing pressure of 56 psig, a casing pressure of 8 psig, cumulative totals are the same as yesterday -- The TBC #3 was shut-in with a tubing pressure of 3.5 psig. -- ORW #1 was flowing with a tubing pressure of 14 psig, a morning gas volume of 15.18 mcf and a flow rate of 15.18 mcf/day, Cumulative total 601.49 mcf, on a (10/64" choke) -- The ORW #2 was flowing with a tubing pressure of 47 psig, morning gas volume of 11.06 mcf and a flow rate of 10.75 mcf/day, cumulative total 1,197.05 mcf on a (6/64" choke) -- The ORW #3 well was shut-in with no gauge. ORW #4 was shut-in with a tubing pressure of 16 psig -- The BC-2 well was shut-in with 52 psi and locked behind a fence GPS Reading on this well is North 30dg 1' 0.0" West 91dg 9' 11.5" -- There will only be this report today --

---

**CONFIDENTIALITY NOTICE**

This email communication may contain confidential information which also may be legally privileged and is intended only for the use of the intended recipients identified above. If you are not the intended recipient of this communication, you are hereby notified that any unauthorized review, use, dissemination, distribution, downloading, or copying of this communication is strictly prohibited. If you are not the intended recipient and have received this communication in error, please immediately notify us by reply email, delete the communication and destroy all copies.