

NARRATIVE REPORT

DNR/Office of Conservation
Operations Division

Serial Number	Date 08/06/12	Operator ()
Lease Name		Address
Location (Sec, Twp, Rng / Parish) Assumption		
Field Napoleonville	(7010)	Phone () -
		Contact

R E M A R K S

Bayou Corne Project

Flew over the sinkhole this morning and it hadn't appeared to have changed any --

The 4 1/2" csg stub is still bubbling around the base of the csg and there were no changes --

By looking at other pictures of the 4 1/2" csg from the past, the csg is leaning
the same now as it was then --

Went to the sinkhole and took samples of the fluids in the area and gave the samples to DEQ
to have analyzed -- While there, an offshore fishing reel with a weight on the line was dropped in the
sinkhole and tagged out at 116 meters - Roughly 381' - The size of the pit was taken with a rang finder
and found from one side to the other was about 372' +- --- The samples that were taken on the fourth
came back showing that there were traces of oil and diesel with the chlorides 10 to 20 times
higher then normal -- Made a trip in the boat to check the bubbles in Bayou Corne and there
were no changes in the bubbles --

Michael Theriot

7:00 am to 8:00 am = 1 Hr Over

8:00 am to 4:30 pm = 8 Hrs Regular

4:30 pm to 10:30 pm = 6 Hrs Over

1/2 Hr off for Dinner

Total Hrs = 15 Hrs