



Texas Brine Company, LLC

1301 Highway 70
Belle Rose, LA 70341
Phone: 985-369-6657
Fax: 985-369-7873



January 7, 2014

Commissioner James H. Welsh
P.O. Box 94275
Baton Rouge, LA 70804

RE: In response to State of Louisiana Department of Natural Resources Office of Conservation's Second Amendment to Declaration of Emergency and Directive

Commissioner Welsh,

In response to the Second Amendment and Declaration of Emergency and Directive order issued by the Louisiana Department of Natural Resources (LDNR), Office of Conservation on September 25, 2012, Texas Brine Company, LLC (TBC) understands the seven items listed in the document.

In the above mentioned, TBC was specifically directed and ordered to perform certain tasks outlined in the above mentioned document. Below are the required responses, as directed.

1. TBC's counsel provided LDNR legal counsel with a response to Directives 1-3 on September 28, 2012.
2. TBC understands Directive 4, which is to provide all daily logs and field notes from all contractors conducting investigation into subsidence and natural gas bubbling. The Daily Action Summary and results for current information can be found in the Attachment section of this report.
3. TBC understands Directive 5, which directs TBC to immediately allow for split or share any sample taken on site related to Well 3A (Serial Number 974265), the cavern, other wells facilities or other site locations. The Daily Action Summary of today's collection can be found in Attachment section of this report.
4. TBC understands Directive 6, which directs TBC to immediately report the results (final and preliminary) of any tests, logs samples or data collection performed on Well 3A, the cavern, other wells, facilities or site locations that indicate a change in any previously known conditions related to the investigation of the subsidence or natural gas bubbling

events, and continue to report any such results. The Daily Action Summary and the Results related to this Directive can be found in Attachment section of this report.

5. TBC understands the Directive 7, which states that TBC will provide a daily summary of all tests, or logs performed or samples taken from Well 3A and the cavern as well as any results of those tests or logs, including preliminary as of September 25, 2012 and going forward. The Daily Summary and Results related to this Directive can be found in Attachment section of this report.

Please note that the drilling rig used for the Observation Well 3A has been removed and the site is being rigged down and returned to pre-drilling condition. As such, daily drilling reports for this well have ceased. Plans are being made for longer term potential gas venting/flaring requirements and possible hydrocarbon material recover from Well 3A.

In addition, previous daily summary reports issued to LDNR have included significant duplicate information as there is a fair amount of overlap in the information requested in each of the Directives included in the September 25, 2012 order. All requested information associated with the Directives issued in the September 25, 2012 order are included in the Attachment section of this report.

TBC believes that the submittal of this report satisfies the requirements of the Declaration of Emergency and Directive issued on September 25, 2012. As directed this report is submitted by email to conservationorder@la.gov, ref. "Emergency Declaration-Texas Brine Company LLC-9/25/2012.



Bruce E. Martin

Vice President, Operations

Texas Brine Company, LLC

Summary Table for Daily Events

TBC Oxy Grand Bayou Data Management-Environmental										
Contractor	Responsibilities	Collected By		Date Collected	Delivered to Lab	Results from Lab	Laboratory	Method	Date to Agencies	
Sage	Stationary Air Monitoring	No Sage personnel onsite, Roxana Dubose - 07:00 - 17:00		1/6/2014	NA	NA	NA	NA	1/7/2014	
	Residential Air Monitoring	Sage has been requested to suspend bimonthly residential air monitoring. Therefore, Sage will discontinue these activities.		NA	NA	NA	NA	NA	NA	
	Gas Seep Sampling	No work performed		1/6/2014	NA	NA	NA	NA	NA	
	Well Gas Sampling	No work performed		1/6/2014	NA	NA	NA	NA	NA	
	Under Slab Gas Sampling	No work performed		1/6/2014	NA	NA	NA	NA	NA	
	Indoor Air Monitoring	No work performed		1/6/2014	NA	NA	NA	NA	NA	
Respec	Inclinometers/Tilt Meters/Transducers	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	InSAR Reflector Installations	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Subsidence Survey-Fenstermaker	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Shallow Geophone Installation	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Deep Geophone Installation	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Amendment #3, Directive #2	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Expansion of geoprobe gas sampling locations	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	DPVE	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Abandon Casing Survey	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Passive Vent Well at NSDBS56	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	MIHPT	1/6/2014	No work Conducted	NA	NA	NA	NA	NA	NA	
	Miller	Weekly Stability Survey	NA		January 6, 2014	NA	NA	NA	NA	NA
		Misc. Survey Work	NA		January 6, 2014	NA	NA	NA	NA	NA
Sinkhole Hydro/Perimeter Survey		NA		January 6, 2014	NA	NA	NA	NA	NA	
Pisani	Surface Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	Sinkhole	NA		January 6, 2014	NA	NA	NA	NA	NA	
	Industrial Well Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	MRAA Well Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	GP/ORW Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	Cavern Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	Discharge/Outfall Water	NA		January 6, 2014	NA	NA	NA	NA	NA	
	Geoprobe Wells	NA		January 6, 2014	NA	NA	NA	NA	NA	
Grand Bayou Well 3A										
Daily Operations at 3A		Summary of Today's events								
		Oxy 3A								
1/7/2014		7:00am	1083.75	1/7/2014						
1/7/2014		Relief Well #1								
		See ORW-01 Flare Spreadsheet (will be provided 1/2/14)								

Attachments

Daily Action Summary

January 6, 2014

Sinkhole Perimeter Air Monitoring and Neighborhood Air Monitoring

- The following locations are equipped with solar-powered weather boxes: Pad #9, TR-1a, ORW-11a, ORW-9a, ORW-5, and PVW-BS-56a. And, the following locations are equipped with electrical power: ORW-49-WH and ORW-50-WH. Thus, daily monitor change-out is no longer necessary. All monitors will continue to be calibrated and serviced as necessary.
- No Sage personnel onsite.
- Roxana Dubose of Code Red (monitor sub-contractor) onsite from 07:00 to 17:00. Assisted in maintenance of the monitoring equipment as necessary.

NOTE: As discussed on the 01/05/2014 Daily Action Summary, data had to be manually retrieved from internal data loggers from all active sinkhole units due to radio signal issues, which began at approximately 17:00 on 01/05/2014. The internal data logger for RTU-3, located at ORW-9a, was not set to internally record CO and VOC. The onsite technician has corrected the internal data logger settings for RTU-3.

Additionally, beginning at approximately 18:40 on 01/06/2014, RTU-14, located at ORW-50-WH, recorded elevated O₂ readings, causing the monitor to intermittently alarm. The highest instantaneous O₂ reading recorded was 29.2%. Temperatures were below freezing during this time period.

Residential Air Monitoring

- Sage has been requested to suspend bimonthly residential air monitoring. Therefore, Sage will discontinue these activities. The last event was conducted on March 26, 2013.

Gas Seep Sampling

- Not Scheduled

Well Gas Sampling

- Not Scheduled

Under Slab Gas Sampling

- Not Scheduled

Air Indoor Monitoring

- Not Scheduled

Texas Brine - Belle Rose, Louisiana
Hourly Air Monitoring Data
Neighborhood Monitoring

*Time indicates start of time period (ex. 12:00:00 AM gives the time period 12:00:00 AM to 12:59:59 AM)

Date-Time *	Observation Relief Well -49 at the Well Head			Observation Relief Well - 50 at the Well Head			Passive Vent Well -56		
	ORW-49-WH			ORW-50-WH			PVW-BS-56a		
	H2S (ppm)	LEL (%)	O2 (%)	H2S (ppm)	LEL (%)	O2 (%)	H2S (ppm)	LEL (%)	O2 (%)
01/06/2014 01:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 02:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 03:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 04:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 05:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 06:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 07:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 08:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 09:00:00 AM	<1.0	0.0	20.6	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 10:00:00 AM	<1.0	0.0	20.6	<1.0	0.0	20.9	0.0	0.0	21.3
01/06/2014 11:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 12:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	21.3
01/06/2014 01:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 02:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.0
01/06/2014 03:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 04:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.1
01/06/2014 05:00:00 PM	<1.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 06:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	24.1	0.0	0.0	20.9
01/06/2014 07:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 08:00:00 PM	<1.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 09:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	21.1	0.0	0.0	20.9
01/06/2014 10:00:00 PM	<1.0	0.0	20.6	<1.0	0.0	21.4	0.0	0.0	20.9
01/06/2014 11:00:00 PM	<1.0	0.0	20.6	<1.0	0.0	21.1	0.0	0.0	20.9
01/07/2014 12:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	21.1	0.0	0.0	20.9

Notes:

Beginning at approximately 06:40 PM on 01/06/2014, RTU-14, located at ORW-50-WH, recorded elevated O2 readings, causing the monitor to intermittently alarm. The highest instantaneous O2 reading recorded was 29.2%. Temperatures were below freezing during this time period.

Texas Brine - Belle Rose, Louisiana
Hourly Air Monitoring Data
Sinkhole Perimeter Monitoring

*Time indicates start of time period (ex. 12:00:00 AM gives the time period 12:00:00 AM to 12:59:59 AM)

Date-Time *	Observation Relief Well -5					Observation Relief Well - 9					Observation Relief Well -11					South of OG3A-1					Onsite Trailers				
	ORW-5					ORW-9a					ORW-11a					Pad #9					TR-1a				
	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	SO2 (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)
01/06/2014 01:00:00 AM	0.0	0.0	0.0	0.0	20.9	See Note	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 02:00:00 AM	0.0	0.0	0.0	0.0	20.9		0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 03:00:00 AM	0.0	0.0	0.0	0.0	20.9		0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 04:00:00 AM	0.0	0.0	0.0	0.0	20.7		0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 05:00:00 AM	0.0	0.0	0.0	0.0	20.5		0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 06:00:00 AM	0.0	0.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 07:00:00 AM	<1.0	0.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 08:00:00 AM	<1.0	0.0	0.0	0.0	20.5	<1.0	0.0	<1.0	0.0	20.8	1.1	0.0	<1.0	0.0	20.5	0.0	<1.0	0.0	0.0	20.8	<1.0	<1.0	<1.0	0.0	20.9
01/06/2014 09:00:00 AM	<1.0	0.0	<1.0	0.0	20.8	<1.0	0.0	0.0	0.0	20.8	<1.0	0.0	0.0	20.7	0.0	0.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 10:00:00 AM	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	
01/06/2014 11:00:00 AM	<1.0	0.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 12:00:00 PM	<1.0	0.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 01:00:00 PM	<1.0	0.0	0.0	0.0	21.2	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 02:00:00 PM	<1.0	0.0	0.0	0.0	21.1	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 03:00:00 PM	0.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	
01/06/2014 04:00:00 PM	0.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	
01/06/2014 05:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.8	<1.0	0.0	0.0	20.8	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.8	
01/06/2014 06:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.6	<1.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.6	
01/06/2014 07:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.6	<1.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 08:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	20.6	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 09:00:00 PM	0.0	<1.0	0.0	0.0	20.8	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 10:00:00 PM	0.0	<1.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 11:00:00 PM	0.0	<1.0	0.0	0.0	20.6	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 12:00:00 AM	0.0	<1.0	0.0	0.0	20.5	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	

Notes:
Data had to be manually retrieved from internal data loggers from all active units due to radio signal issues, which began at approximately 05:00 PM on 01/05/2014. The internal data logger for RTU-3, located at ORW-9a, was not set to internally record CO and VOC. The onsite technician has corrected the internal data logger settings for RTU-3.

Texas Brine - Belle Rose, Louisiana
Hourly Air Monitoring Data
Neighborhood Monitoring

*Time indicates start of time period (ex. 12:00:00 AM gives the time period 12:00:00 AM to 12:59:59 AM)

Date-Time *	Observation Relief Well -49 at the Well Head			Observation Relief Well - 50 at the Well Head			Passive Vent Well -56		
	ORW-49-WH			ORW-50-WH			PVW-BS-56a		
	H2S (ppm)	LEL (%)	O2 (%)	H2S (ppm)	LEL (%)	O2 (%)	H2S (ppm)	LEL (%)	O2 (%)
01/06/2014 05:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 06:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 07:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 08:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 09:00:00 AM	<1.0	0.0	20.6	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 10:00:00 AM	<1.0	0.0	20.6	<1.0	0.0	20.9	0.0	0.0	21.3
01/06/2014 11:00:00 AM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 12:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	21.3
01/06/2014 01:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 02:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.0
01/06/2014 03:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.2
01/06/2014 04:00:00 PM	0.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	21.1
01/06/2014 05:00:00 PM	<1.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 06:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	24.1	0.0	0.0	20.9
01/06/2014 07:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 08:00:00 PM	<1.0	0.0	20.9	0.0	0.0	20.9	0.0	0.0	20.9
01/06/2014 09:00:00 PM	<1.0	0.0	20.9	<1.0	0.0	21.1	0.0	0.0	20.9
01/06/2014 10:00:00 PM	<1.0	0.0	20.6	<1.0	0.0	21.4	0.0	0.0	20.9
01/06/2014 11:00:00 PM	<1.0	0.0	20.6	<1.0	0.0	21.1	0.0	0.0	20.9
01/07/2014 12:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	21.1	0.0	0.0	20.9
01/07/2014 01:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	21.0	0.0	0.0	20.9
01/07/2014 02:00:00 AM	<1.0	0.0	20.4	<1.0	0.0	20.6	0.0	0.0	20.9
01/07/2014 03:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	20.7	0.0	0.0	20.9
01/07/2014 04:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	20.9	0.0	0.0	25.1
01/07/2014 05:00:00 AM	<1.0	0.0	20.5	<1.0	0.0	21.2	0.0	0.0	25.2

Notes:

Beginning at approximately 06:40 PM on 01/06/2014, RTU-14, located at ORW-50-WH, recorded elevated O2 readings, causing the monitor to intermittently alarm. The highest instantaneous O2 reading recorded was 29.2%. Temperatures were below freezing during this time period.

Beginning at approximately 04:52 AM on 01/07/2014, RTU-15, located at PVW-BS-56a, recorded elevated O2 readings, causing the monitor to intermittently alarm. The highest instantaneous O2 reading recorded was 30.0%. Temperatures were below freezing during this time period.

Texas Brine - Belle Rose, Louisiana
Hourly Air Monitoring Data
Sinkhole Perimeter Monitoring

*Time indicates start of time period (ex. 12:00:00 AM gives the time period 12:00:00 AM to 12:59:59 AM)

Date-Time *	Observation Relief Well -5					Observation Relief Well -9					Observation Relief Well -11					South of OG3A-1					Onsite Trailers					
	ORW-5					ORW-9a					ORW-11a					Pad #9					TR-1a					
	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	SO2 (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	CO (ppm)	Non-Methane VOC (ppm)	H2S (ppm)	LEL (%)	O2 (%)	
01/06/2014 05:00:00 AM	0.0	0.0	0.0	0.0	20.5	See Note					20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9
01/06/2014 06:00:00 AM	0.0	0.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 07:00:00 AM	<1.0	0.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 08:00:00 AM	<1.0	0.0	0.0	0.0	20.5	<1.0	0.0	<1.0	0.0	20.8	1.1	0.0	<1.0	0.0	20.5	0.0	<1.0	0.0	0.0	20.8	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 09:00:00 AM	<1.0	0.0	<1.0	0.0	20.8	<1.0	0.0	0.0	0.0	20.8	<1.0	0.0	0.0	0.0	20.7	0.0	0.0	0.0	0.0	20.9	<1.0	<1.0	<1.0	0.0	20.9	
01/06/2014 10:00:00 AM	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	
01/06/2014 11:00:00 AM	<1.0	0.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 12:00:00 PM	<1.0	0.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 01:00:00 PM	<1.0	0.0	0.0	0.0	21.2	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 02:00:00 PM	<1.0	0.0	0.0	0.0	21.1	<1.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	<1.0	0.0	20.9	
01/06/2014 03:00:00 PM	0.0	0.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	
01/06/2014 04:00:00 PM	0.0	0.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.9	<1.0	0.0	0.0	0.0	20.9	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.9	
01/06/2014 05:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.8	<1.0	0.0	0.0	0.0	20.8	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.8	
01/06/2014 06:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.6	<1.0	0.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.6	
01/06/2014 07:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.6	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 08:00:00 PM	0.0	<1.0	0.0	0.0	20.9	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.6	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 09:00:00 PM	0.0	<1.0	0.0	0.0	20.8	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 10:00:00 PM	0.0	<1.0	0.0	0.0	20.7	0.0	<1.0	0.0	0.0	20.5	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/06/2014 11:00:00 PM	0.0	<1.0	0.0	0.0	20.6	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 12:00:00 AM	0.0	<1.0	0.0	0.0	20.5	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 01:00:00 AM	0.0	<1.0	0.0	0.0	20.5	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.4	0.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 02:00:00 AM	0.0	<1.0	0.0	0.0	20.4	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 03:00:00 AM	0.0	<1.0	0.0	0.0	20.3	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.5	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 04:00:00 AM	0.0	<1.0	0.0	0.0	20.3	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.4	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.5	
01/07/2014 05:00:00 AM	0.0	<1.0	0.0	0.0	20.3	0.0	<1.0	0.0	0.0	20.4	<1.0	0.0	0.0	0.0	20.4	<1.0	<1.0	0.0	0.0	20.9	0.0	0.0	0.0	0.0	20.4	

Notes:

Data had to be manually retrieved from internal data loggers from all active units due to radio signal issues, which began at approximately 05:00 PM on 01/05/2014. The internal data logger for RTU-3, located at ORW-9a, was not set to internally record CO and VOC. The onsite technician has corrected the internal data logger settings for RTU-3.

RESPEC Consulting & Services

Texas Brine, L.L.C.

Assumption Parish, Louisiana

Daily Field Report

Report By: Crystal Hocking

Date: 1/6/2014

Company: RESPEC

Job #: 2241

Personnel	Company	Job Title
Eric Krantz	RESPEC	Staff Engineer

Time Onsite: Start Time: NA End Time: NA

DAILY ACTIVITY:

No Field Work Conducted. Eric Krantz arrived on site.

Instrumentation Program:

No Work Conducted.

Other Programs:

Passive Vent-GP-56: No work conducted by RESPEC.

PROPOSED SCHEDULE:

Instrumentation Program:

RESPEC will to be on-site January 7^h, 2014. Planned general site maintenance visits and battery change at inclinometer IPI-21.

Other Programs:

Passive Vent Wells: RESPEC will work with WHE and TBC to begin demobilizing the barge from PVW-56 (located near the former location of NSDBS-056).

Initials: CMH