



Pre-Excavation Photo 1- E



Pre-Excavation Photo 2 - SE




Pre-Excavation Photo 3 - N



Pre-Excavation Photo 4 - WNW




Pre-Excavation Photo 5 - NW



Pre-Excavation Photo 6 - NE



Pre-Excavation Photo 7 - NE



Pre-Excavation Photo 8 - W



Pre-Excavation Photo 9



Pre-Excavation Photo 10 - E



Pre-Excavation Photo 11 - NW




Pre-Excavation Photo 12 - NW



Pre-Excavation Photo 13 - N



Pre-Excavation Photo 14 - NE




Pre-Excavation Photo 15 - N



Pre-Excavation Photo 16 - W



Pre-Excavation Photo 17 - E



Pre-Excavation Photo 18



Pre-Excavation Photo 19 - S



Pre-Excavation Photo 20 - S



Pre-Excavation Photo 21 - E



DSCN0739



DSCN0740




DSCN0741



DSCN0742



DSCN0743



DSCN0744



DSCN0745



DSCN0746




DSCN0747



DSCN0748



DSCN0749



DSCN0750



DSCN0751



DSCN0752



DSCN0753



DSCN0754



DSCN0755



DSCN0756



DSCN0757



DSCN0758



IMG_3765



IMG_3766



IMG_3767



IMG_3768



IMG_3769



IMG_3770



IMG_3771



IMG_3772



IMG_3773




IMG_3774



IMG_3775



IMG_3776



IMG_3777



IMG_3778



IMG_3779




IMG_3780



IMG_3781



IMG_3782



IMG_3783



IMG_3784



IMG_3785



IMG_3786



IMG_3787



IMG_3788




IMG_3789



IMG_3790



IMG_3791



IMG_3792



IMG_3793



IMG_3794



IMG_3795



IMG_3796



IMG_3797



IMG_3798



IMG_3799



IMG_3800



IMG_3801



DSCN0759



DSCN0760



IMG_3802



DSCN0761



IMG_3803



IMG_3804



IMG_3805



IMG_3806



IMG_3807



IMG_3808



IMG_3809



IMG_3810



IMG_3811



IMG_3812



IMG_3813



IMG_3814



IMG_3817



IMG_3815



IMG_3818



IMG_3819



IMG_3820



IMG_3821



IMG_3822



IMG_3823



IMG_3824



IMG_3825



IMG_3826



IMG_3827



IMG_3828



IMG_3829



IMG_3830



IMG_3831



IMG_3832



IMG_3833



IMG_3834



IMG_3835



IMG_3836



IMG_3837



IMG_3838



IMG_3839



IMG_3840



IMG_3841



IMG_3842



IMG_3843



EWL-MH5



EWL-MH8



EWL-MH9




EWL-MH10



EWL-MH11



EWL-MH12



EWL-MH18



EWL-MH25



EWL-MH35



EWL-MH38



IMG_1584



IMG_1585



IMG_1586



IMG_1587



IMG_1588



IMG_1589



EWL-MH39



IMG_1590




IMG_1591



IMG_1592



IMG_1593



IMG_1594



IMG_1595



IMG_1596



IMG_1597



IMG_1598



IMG_1599



IMG_1600



IMG_1601



IMG_1602



IMG_1603



IMG_1604



IMG_1605



IMG_1606



EWL-MH40



EWL-MH41



EWL-MH42



EWL-MH43



EWL-MH44



EWL-MH45



EWL-MH 1



EWL-MH 2



EWL-MH 3



EWL-MH 4




EWL-MH 6




EWL-MH 7



EWL-MH13



EWL-MH14



EWL-MH15



EWL-MH16



EWL-MH17



EWL-MH19



EWL-MH20



EWL-MH21



EWL-MH22



EWL-MH23



EWL-MH24



EWL-MH26



EWL-MH27



EWL-MH28




EWL-MH29



EWL-MH30



EWL-MH31



EWL-MH32



EWL-MH33



EWL-MH34



EWL-MH36



EWL-MH37



Station 1_1 2014.12.15



Station 1_2 2014.12.15



Station 1_3 2014.12.15



Station 1_4 2014.12.15



Station 2_1 2014.12.15



Station 2_2 2014.12.15



Station 2_3 2014.12.15




Station 2_4 2014.12.15



Station 3_1 2014.12.15



Station 3_2 2014.12.15



Station 3_3 2014.12.15



Station 3_4 2014.12.15



Station 4_1 2014.12.15



Station 4_2 2014.12.15



Station 4_3 2014.12.15



Station 4_4 2014.12.15



Station 5_1 2014.12.15



Station 5_2 2014.12.15



Station 5_3 2014.12.15



Station 5_4 2014.12.15

Photographs
Oversite of Pit Closure & Remediation
November 17, 2014
East White Lake 07-165
Vermilion Parish, LA

<u>Photo ID</u>	<u>Photographer</u>	<u>Date</u>	<u>Time Stamp</u>	<u>Direction</u>	<u>Description</u>
Pre-Excavation Photo 1	LRC	11/17/2014	11:19	E	General Pre-Excavation Conditions
Pre-Excavation Photo 2	LRC	11/17/2014	11:19	SE	General Pre-Excavation Conditions
Pre-Excavation Photo 3	LRC	11/17/2014	11:19	N	General Pre-Excavation Conditions
Pre-Excavation Photo 4	LRC	11/17/2014	11:20	WNW	General Pre-Excavation Conditions
Pre-Excavation Photo 5	LRC	11/17/2014	11:20	NW	General Pre-Excavation Conditions
Pre-Excavation Photo 6	LRC	11/17/2014	11:21	NE	General Pre-Excavation Conditions
Pre-Excavation Photo 7	LRC	11/17/2014	11:21	NE	General Pre-Excavation Conditions
Pre-Excavation Photo 8	LRC	11/17/2014	11:22	W	General Pre-Excavation Conditions
Pre-Excavation Photo 9	LRC	11/17/2014	11:22		General Pre-Excavation Conditions
Pre-Excavation Photo 10	LRC	11/17/2014	11:22	E	General Pre-Excavation Conditions
Pre-Excavation Photo 11	LRC	11/17/2014	11:22	NW	General Pre-Excavation Conditions
Pre-Excavation Photo 12	LRC	11/17/2014	11:22	NW	General Pre-Excavation Conditions
Pre-Excavation Photo 13	LRC	11/17/2014	11:22	N	General Pre-Excavation Conditions
Pre-Excavation Photo 14	LRC	11/17/2014	11:24	NE	General Pre-Excavation Conditions
Pre-Excavation Photo 15	LRC	11/17/2014	11:24	N	General Pre-Excavation Conditions
Pre-Excavation Photo 16	LRC	11/17/2014	11:24	W	General Pre-Excavation Conditions
Pre-Excavation Photo 17	LRC	11/17/2014	11:26	E	General Pre-Excavation Conditions
Pre-Excavation Photo 18	LRC	11/17/2014	11:26		General Pre-Excavation Conditions
Pre-Excavation Photo 19	LRC	11/17/2014	11:26	S	General Pre-Excavation Conditions
Pre-Excavation Photo 20	LRC	11/17/2014	11:26	S	General Pre-Excavation Conditions
Pre-Excavation Photo 21	LRC	11/17/2014	11:27	E	General Pre-Excavation Conditions
DSCN0739	LRC	11/20/2014	11:29	N	Beginning of excavation.
DSCN0740	LRC	11/20/2014	11:29	NE	Same as above.
DSCN0741	LRC	11/20/2014	12:00	E	Canal N of Sed 15 Area
DSCN0742	LRC	11/20/2014	12:51	W	Soil - wet clay
DSCN0743	LRC	11/20/2014	12:52	W	Same as above.
DSCN0744	LRC	11/20/2014	13:17	W	Same as above.
DSCN0745	LRC	11/21/2014	11:03		Continued Excavation
DSCN0746	LRC	12/1/2014	9:03	SW	Bank prior to sheet wall.
DSCN0747	LRC	12/1/2014	11:34	NE	Water level in excavated pit.
DSCN0748	LRC	12/1/2014	11:35	NW	Same as above.
DSCN0749	LRC	12/1/2014	4:34	SE	Same as above.
DSCN0750	LRC	12/1/2014	4:36	W	Barge loaded with backfill.
DSCN0751	LRC	12/1/2014	4:36	W	Same as above.
DSCN0752	LRC	12/1/2014	4:41	E-SE	Installing sheet wall.
DSCN0753	LRC	12/1/2014	4:43	S	Same as above.
DSCN0754	LRC	12/1/2014	4:45	S	Same as above.
DSCN0755	LRC	12/1/2014	4:45	S	Same as above.
DSCN0756	LRC	12/2/2014	9:07	S	Installing sheet wall.
DSCN0757	LRC	12/2/2014	11:29	E	Same as above.
DSCN0758	LRC	12/2/2014	11:29	E	Same as above.
IMG_3765	TGC	12/2/2014	13:47	NE	Install of sheet piles, 22 total.
IMG_3766	TGC	12/2/2014	13:47	SW	Same as above.
IMG_3767	TGC	12/2/2014	13:47	SE	Step-out excavation.
IMG_3768	TGC	12/2/2014	13:52	NE	Installation of eastern corner pile.
IMG_3769	TGC	12/2/2014	13:57	SE	Same as above.
IMG_3770	TGC	12/2/2014	13:59	E	Same as above.
IMG_3771	TGC	12/2/2014	14:02	E	Using excavator bucket to push eastern corner sheet pile in place.
IMG_3772	TGC	12/2/2014	14:51	SW	Using excavator bucket to push western corner sheet pile in place.
IMG_3773	TGC	12/2/2014	16:02	SE	Completed Sheet pile wall.
IMG_3774	TGC	12/2/2014	16:02	N	Barge orientation at the end of the day.
IMG_3775	TGC	12/2/2014	16:02	NE	Completed Sheet pile wall and caution tape restored.
IMG_3776	TGC	12/3/2014	8:01	NE	Tugboat moving barge into place.
IMG_3777	TGC	12/3/2014	8:01	N	Same as above.

Photographs
Oversite of Pit Closure & Remediation
November 17, 2014
East White Lake 07-165
Vermilion Parish, LA

Photo ID	Photographer	Date	Time Stamp	Direction	Description
IMG_3778	TGC	12/3/2014	8:24	NE	Completed eastern soil plug between sheet piles and land.
IMG_3779	TGC	12/3/2014	8:25	NE	Pump mobilization.
IMG_3780	TGC	12/3/2014	8:25	E	Same as above.
IMG_3781	TGC	12/3/2014	8:47	SW	Completed western soil plug between sheet piles and land.
IMG_3782	TGC	12/3/2014	8:58	NE	Overall site progression with pumping, visible change in water line.
IMG_3783	TGC	12/3/2014	8:58	NE	Same as above.
IMG_3784	TGC	12/3/2014	9:25	S	Beginning of step-out backfill.
IMG_3785	TGC	12/3/2014	9:25	NE	Filling of barge with water from excavation.
IMG_3786	TGC	12/3/2014	9:37	E	Completed backfill of step-out area.
IMG_3787	TGC	12/3/2014	10:12	SE	Same as above.
IMG_3788	TGC	12/3/2014	10:33	SW	Same as above.
IMG_3789	TGC	12/3/2014	11:35	SW	Same as above, and start berm construction.
IMG_3790	TGC	12/3/2014	12:51	SW	Progression of berm construction to support sheet pile.
IMG_3791	TGC	12/3/2014	12:52	NE	Setup for backfill/pumping.
IMG_3792	TGC	12/3/2014	14:22	W	Solids surfacing during backfill.
IMG_3793	TGC	12/3/2014	14:22	N	Progression of berm construction to prevent leaks into site.
IMG_3794	TGC	12/3/2014	14:23	N	Same as above, with solids movement occurring.
IMG_3795	TGC	12/3/2014	15:11	SW	Overview of site progress.
IMG_3796	TGC	12/3/2014	15:14	W	Using excavator and tugboat to orient barges.
IMG_3797	TGC	12/3/2014	15:28	S	Berm progression and solids near the surface.
IMG_3798	TGC	12/3/2014	15:28	SW	Same as above.
IMG_3799	TGC	12/3/2014	17:00	SE	Solids during backfill.
IMG_3800	TGC	12/3/2014	17:00	SW	Overall berm progress.
IMG_3801	TGC	12/3/2014	17:00	E	Overall Site progress.
IMG_3802	TGC	12/4/2014	7:20	S	Site condition in morning.
IMG_3803	TGC	12/4/2014	13:55	NE	Placement of silt boom.
IMG_3804	TGC	12/4/2014	13:55	SW	Same as above.
IMG_3805	TGC	12/4/2014	13:55	S	Alignment of barges.
IMG_3806	TGC	12/4/2014	13:56	S	Caution tape around construction area.
IMG_3807	TGC	12/4/2014	14:21	W	Overview of site condition with caution tape and completed berm.
IMG_3808	TGC	12/4/2014	14:21	SW	Same as above.
IMG_3809	TGC	12/4/2014	14:22	SE	Same as above.
IMG_3810	TGC	12/4/2014	14:22	S	Same as above.
IMG_3811	TGC	12/4/2014	14:22	E	Same as above.
IMG_3812	TGC	12/4/2014	14:25	S	Same as above.
IMG_3813	TGC	12/4/2014	14:25	S	Same as above.
IMG_3814	TGC	12/4/2014	14:25	SW	Same as above.
IMG_3815	TGC	12/8/2014	8:08	S	Current site conditions in morning.
IMG_3817	TGC	12/8/2014	8:54	W	Placement of oil boom and movement of barges.
IMG_3818	TGC	12/8/2014	10:23	E	Removal of pump for remediation area.
IMG_3819	TGC	12/8/2014	11:38	NE	Arrival of sump pump to remove solids from excavation area.
IMG_3820	TGC	12/8/2014	11:41	E	Same as above.
IMG_3821	TGC	12/8/2014	11:46	E	Same as above.
IMG_3822	TGC	12/8/2014	12:15	S	Same as above.
IMG_3823	TGC	12/8/2014	12:22	S	Hooking up sump pump to discharge hose.
IMG_3824	TGC	12/8/2014	12:24	SW	Using the excavator to lower pump into the site.
IMG_3825	TGC	12/8/2014	12:25	S	Same as above.
IMG_3826	TGC	12/8/2014	12:28	SW	Same as above.
IMG_3827	TGC	12/8/2014	12:41	S	Same as above.
IMG_3828	TGC	12/8/2014	12:52	SW	Same as above.

Photographs
Oversite of Pit Closure & Remediation
November 17, 2014
East White Lake 07-165
Vermilion Parish, LA

Photo ID	Photographer	Date	Time Stamp	Direction	Description
IMG_3829	TGC	12/8/2014	13:03	E	Same as above.
IMG_3830	TGC	12/8/2014	13:03	SE	Solids surfacing during backfill and pumping.
IMG_3831	TGC	12/8/2014	13:21	W	Cleaning pump to remove organic debris.
IMG_3832	TGC	12/8/2014	13:29	SW	Creating a low point within the site for the water to gather.
IMG_3833	TGC	12/8/2014	13:31	W	Laying visqueen to prepare for manual removal of muck.
IMG_3834	TGC	12/8/2014	13:37	SW	Same as above.
IMG_3835	TGC	12/8/2014	14:00	W	Manual removal of wet solids with excavator.
IMG_3836	TGC	12/8/2014	14:00	W	Same as above.
IMG_3837	TGC	12/8/2014	14:37	SW	Overall site progress.
IMG_3838	TGC	12/8/2014	14:37	SW	Manual removal of wet solids with excavator.
IMG_3839	TGC	12/8/2014	15:00	S	Using the excavator to lower pump into the site.
IMG_3840	TGC	12/8/2014	15:53	W	Overall site conditions at the end of the day.
IMG_3841	TGC	12/8/2014	15:58	W	Same as above.
IMG_3842	TGC	12/8/2014	16:12	SW	Same as above.
IMG_3843	TGC	12/8/2014	16:12	SW	Same as above.
DSCN0759	LRC	12/4/2014	8:19	SW	Sheet wall installed. Water level in excavation.
DSCN0760	LRC	12/4/2014	8:19	S	Same as above.
DSCN0761	LRC	12/4/2014	11:56	SW	Same as above.
EWL-MH 1	MMH	12/9/2014	7:36	SW	Lowering pump to continue discharging water.
EWL-MH 2	MMH	12/9/2014	7:57	SW	Continue excavating wet solids.
EWL-MH 3	MMH	12/9/2014	9:18	SW	Began backfilling where water was seeping through from marsh.
EWL-MH 4	MMH	12/9/2014	9:40	S	Continue excavating wet solids.
EWL-MH 5	MMH	12/9/2014	10:47	S	Same as above
EWL-MH 6	MMH	12/9/2014	12:53	SW	Continue backfilling.
EWL-MH 7	MMH	12/9/2014	12:53	S	Same as above
EWL-MH 8	MMH	12/9/2014	13:40	SW	Same as above
EWL-MH 9	MMH	12/10/2014	9:08	N	Natural ground at sheet pilings on NE corner.
EWL-MH 10	MMH	12/10/2014	10:04	SW	Continue backfilling.
EWL-MH 11	MMH	12/10/2014	12:42	W	Compacting backfill.
EWL-MH 12	MMH	12/11/2014	8:53	W	Backfilled area prior to removing sheet wall.
EWL-MH 13	MMH	12/11/2014	9:12	E	South side of backfilled area prior to removing sheet wall.
EWL-MH 14	MMH	12/11/2014	9:12	N	Natural ground at sheet pilings on NW corner.
EWL-MH 15	MMH	12/11/2014	9:12	N	NE Side of backfilled area after sheet pile was removed.
EWL-MH 16	MMH	12/11/2014	10:18	NW	Removal of sheet wall.
EWL-MH 17	MMH	12/11/2014	10:28	W	Sheet wall removal near completion.
EWL-MH 18	MMH	12/11/2014	14:15	N	Same as above
EWL-MH 19	MMH	12/11/2014	14:15	W	Same as above
EWL-MH 20	MMH	12/11/2014	15:48	NE	Same as above
EWL-MH 21	MMH	12/12/2014	8:34	SW	Topsoil placed on southern half of backfilled area.
EWL-MH 22	MMH	12/12/2014	11:00	W	Same as above
EWL-MH 23	MMH	12/12/2014	11:05	NW	Building up the slope to match natural grades on the NW and NE corners. Prior to compaction
EWL-MH 24	MMH	12/12/2014	12:46	W	Same as above
EWL-MH 25	MMH	12/12/2014	12:46	W	Same as above
EWL-MH 26	MMH	12/12/2014	12:48	N	Same as above
EWL-MH 27	MMH	12/12/2014	12:48	NE	Same as above
EWL-MH 28	MMH	12/15/2014	8:42	E	Prior to compaction, no settlement over weekend.
EWL-MH 29	MMH	12/15/2014	8:48	W	Same as above
EWL-MH 30	MMH	12/15/2014	8:48	SW/W	Began compaction
EWL-MH 31	MMH	12/15/2014	9:56	W	Began spreading topsoil over entire disturbed area
EWL-MH 32	MMH	12/15/2014	10:08	E	Continued spreading topsoil, slope meets natural grade at NE corner.
EWL-MH 33	MMH	12/15/2014	10:30	NE	Same as above

Photographs
Oversite of Pit Closure & Remediation
November 17, 2014
East White Lake 07-165
Vermilion Parish, LA

Photo ID	Photographer	Date	Time Stamp	Direction	Description
EWL-MH 34	MMH	12/15/2014	11:14	W	Began rolling out matting.
EWL-MH 35	MMH	12/15/2014	11:15	SW	Grass seed was spread over all topsoil
EWL-MH 36	MMH	12/15/2014	11:18	W	Coconut matting was placed over entire disturbed area.
EWL-MH 37	MMH	12/15/2014	11:30	NW	Same as above
EWL-MH 38	MMH	12/15/2014	11:31	N	Same as above
EWL-MH 39	MMH	12/15/2014	11:56	N	Same as above
Station 1_1 2014.12.15	MMH	12/15/2014	13:44	N/NE	Final permit photograph
Station 1_2 2014.12.15	MMH	12/15/2014	13:44	NE	Final permit photograph
Station 1_3 2014.12.15	MMH	12/15/2014	13:44	E	Final permit photograph
Station 1_4 2014.12.15	MMH	12/15/2014	13:44	E/SE	Final permit photograph
Station 2_1 2014.12.15	MMH	12/15/2014	13:45	NW/N	Final permit photograph
Station 2_2 2014.12.15	MMH	12/15/2014	13:45	N	Final permit photograph
Station 2_3 2014.12.15	MMH	12/15/2014	13:45	NE	Final permit photograph
Station 2_4 2014.12.15	MMH	12/15/2014	13:45	E	Final permit photograph
Station 3_1 2014.12.15	MMH	12/15/2014	13:46	NW	Final permit photograph
Station 3_2 2014.12.15	MMH	12/15/2014	13:46	N	Final permit photograph
Station 3_3 2014.12.15	MMH	12/15/2014	13:46	N/NE	Final permit photograph
Station 3_4 2014.12.15	MMH	12/15/2014	13:46	NE	Final permit photograph
Station 4_1 2014.12.15	MMH	12/15/2014	13:47	W	Final permit photograph
Station 4_2 2014.12.15	MMH	12/15/2014	13:47	NW	Final permit photograph
Station 4_3 2014.12.15	MMH	12/15/2014	13:47	N	Final permit photograph
Station 4_4 2014.12.15	MMH	12/15/2014	13:47	N/NE	Final permit photograph
Station 5_1 2014.12.15	MMH	12/15/2014	13:47	S/SW	Final permit photograph
Station 5_2 2014.12.15	MMH	12/15/2014	13:47	W	Final permit photograph
Station 5_3 2014.12.15	MMH	12/15/2014	13:47	W/NW	Final permit photograph
Station 5_4 2014.12.15	MMH	12/15/2014	13:47	NW	Final permit photograph
EWL-MH 40	MMH	12/15/2015	14:10	N	Cleaned barge ready for demobe.
EWL-MH 41	MMH	12/15/2014	14:19	W	Spud barge ready for demobe.
EWL-MH 42	MMH	12/15/2014	14:26	N	Cleaned barge ready for demobe.
EWL-MH 43	MMH	12/15/2014	14:28	SE	Demobing site.
EWL-MH 44	MMH	12/15/2014	14:28	SE	Demobing site.
EWL-MH 45	MMH	12/15/2014	14:28	SE	Demobing site.
IMG_1584	LRC	12/15/2014	11:44	NW	Coconut matting placed over entire disturbed area.
IMG_1585	LRC	12/15/2014	11:44	N-NW	Same as above.
IMG_1586	LRC	12/15/2014	11:44	N	Same as above.
IMG_1587	LRC	12/15/2014	11:44	N-NE	Same as above.
IMG_1588	LRC	12/15/2014	11:55	NW	Same as above.
IMG_1589	LRC	12/15/2014	11:55	N	Same as above.
IMG_1590	LRC	12/15/2014	12:06	S-SE	Same as above.
IMG_1591	LRC	12/15/2014	12:06	S-SE	Same as above.
IMG_1592	LRC	12/15/2014	12:06	S-SW	Same as above.
IMG_1593	LRC	12/15/2014	12:06	W	Same as above.
IMG_1594	LRC	12/15/2014	12:18	S-SW	Coconut matting placed and boom removed.
IMG_1595	LRC	12/15/2014	12:18	S-SW	Same as above.
IMG_1596	LRC	12/15/2014	12:18	S-SW	Same as above.
IMG_1597	LRC	12/15/2014	12:18	S-SW	Same as above.
IMG_1598	LRC	12/15/2014	12:18	S-SW	Same as above.
IMG_1599	LRC	12/15/2014	12:18	S-SW	Same as above.
IMG_1600	LRC	12/15/2014	12:18	S	Same as above.
IMG_1601	LRC	12/15/2014	12:18	S	Same as above.
IMG_1602	LRC	12/15/2014	12:19	NE	Bank N across canal from SED 15 area
IMG_1603	LRC	12/15/2014	12:19	NE	Bank N across canal from SED 15 area
IMG_1604	LRC	12/15/2014	12:19	E	Bank N across canal from SED 15 area
IMG_1605	LRC	12/16/2014	12:19	E	Bank N across canal from SED 15 area
IMG_1606	LRC	12/17/2014	12:19	N	Bank N across canal from SED 15 area



Pre-Excavation Photo 1- E



Pre-Excavation Photo 2 - SE




Pre-Excavation Photo 3 - N



Pre-Excavation Photo 4 - WNW



Pre-Excavation Photo 5 - NW



Pre-Excavation Photo 6 - NE



Pre-Excavation Photo 7 - NE



Pre-Excavation Photo 8 - W



Pre-Excavation Photo 9



Pre-Excavation Photo 10 - E



Pre-Excavation Photo 11 - NW




Pre-Excavation Photo 12 - NW



Pre-Excavation Photo 13 - N



Pre-Excavation Photo 14 - NE




Pre-Excavation Photo 15 - N



Pre-Excavation Photo 16 - W



Pre-Excavation Photo 17 - E



Pre-Excavation Photo 18



Pre-Excavation Photo 19 - S



Pre-Excavation Photo 20 - S



Pre-Excavation Photo 21 - E



DSCN0739



DSCN0740




DSCN0741



DSCN0742



DSCN0743



DSCN0744



DSCN0745



DSCN0746




DSCN0747



DSCN0748



DSCN0749



DSCN0750



DSCN0751



DSCN0752



DSCN0753



DSCN0754



DSCN0755



DSCN0756



DSCN0757



DSCN0758




IMG_3765



IMG_3766



IMG_3767




IMG_3768



IMG_3769



IMG_3770



IMG_3771



IMG_3772



IMG_3773



IMG_3774



IMG_3775



IMG_3776



IMG_3777



IMG_3778



IMG_3779




IMG_3780



IMG_3781



IMG_3782



IMG_3783



IMG_3784



IMG_3785



IMG_3786



IMG_3787



IMG_3788




IMG_3789



IMG_3790



IMG_3791



IMG_3792



IMG_3793



IMG_3794



IMG_3795



IMG_3796



IMG_3797



IMG_3798



IMG_3799



IMG_3800



IMG_3801



DSCN0759



DSCN0760



IMG_3802



DSCN0761



IMG_3803



IMG_3804



IMG_3805



IMG_3806



IMG_3807



IMG_3808



IMG_3809



IMG_3810



IMG_3811



IMG_3812



IMG_3813



IMG_3814



IMG_3817



IMG_3815



IMG_3818



IMG_3819



IMG_3820



IMG_3821



IMG_3822



IMG_3823



IMG_3824



IMG_3825



IMG_3826



IMG_3827



IMG_3828



IMG_3829



IMG_3830



IMG_3831



IMG_3832



IMG_3833



IMG_3834



IMG_3835



IMG_3836



IMG_3837



IMG_3838



IMG_3839



IMG_3840



IMG_3841



IMG_3842



IMG_3843



EWL-MH5



EWL-MH8



EWL-MH9




EWL-MH10



EWL-MH11



EWL-MH12



EWL-MH18



EWL-MH25



EWL-MH35



EWL-MH38



IMG_1584



IMG_1585



IMG_1586



IMG_1587



IMG_1588



IMG_1589



EWL-MH39



IMG_1590




IMG_1591



IMG_1592



IMG_1593



IMG_1594



IMG_1595



IMG_1596



IMG_1597



IMG_1598



IMG_1599



IMG_1600



IMG_1601



IMG_1602



IMG_1603



IMG_1604



IMG_1605



IMG_1606



EWL-MH40



EWL-MH41



EWL-MH42



EWL-MH43



EWL-MH44



EWL-MH45



EWL-MH 1



EWL-MH 2



EWL-MH 3



EWL-MH 4



EWL-MH 6



EWL-MH 7



EWL-MH13



EWL-MH14



EWL-MH15



EWL-MH16



EWL-MH17



EWL-MH19



EWL-MH20



EWL-MH21



EWL-MH22



EWL-MH23



EWL-MH24



EWL-MH26



EWL-MH27



EWL-MH28




EWL-MH29



EWL-MH30



EWL-MH31



EWL-MH32



EWL-MH33



EWL-MH34



EWL-MH36



EWL-MH37



Station 1_1 2014.12.15



Station 1_2 2014.12.15



Station 1_3 2014.12.15



Station 1_4 2014.12.15



Station 2_1 2014.12.15



Station 2_2 2014.12.15



Station 2_3 2014.12.15




Station 2_4 2014.12.15



Station 3_1 2014.12.15



Station 3_2 2014.12.15



Station 3_3 2014.12.15



Station 3_4 2014.12.15



Station 4_1 2014.12.15



Station 4_2 2014.12.15



Station 4_3 2014.12.15



Station 4_4 2014.12.15



Station 5_1 2014.12.15



Station 5_2 2014.12.15



Station 5_3 2014.12.15



Station 5_4 2014.12.15

Table 1
Photo Log
East White Lake Property
Vermilion Parish, LA

Photo ID	Photographer	Date	Direction	Description
010515 001	RCT	1/5/2015	Northwest	WL-1, hand augering
010515 002	RCT	1/5/2015	East	WL-1 0-2' bgs
010515 003	RCT	1/5/2015	East	WL-1 2-4' bgs
010515 004	RCT	1/5/2015	East	WL-1 4-5.5' bgs
010515 005	RCT	1/5/2015	North	WL-1 5.5-9' bgs (top to right)
010515 006	RCT	1/5/2015	North	WL-1 9-13' bgs (top to right)
0010515 007	RCT	1/5/2015	East	WL-2 0-2' bgs
010515 008	RCT	1/5/2015	East	WL-2 2-4' bgs
010515 009	RCT	1/5/2015	East	WL-2 4-6' bgs
010515 010	RCT	1/5/2015	East	WL-2 6-8' bgs
010515 011	RCT	1/5/2015	East	WL-2 8-10' bgs
010515 012	RCT	1/5/2015	East	WL-2 10-12' bgs
010515 013	RCT	1/5/2015	East	WL-2 12-14' bgs
010515 014	RCT	1/5/2015	East	WL-2 14-16' bgs
010515 015	RCT	1/5/2015	North	WL-2 location
010615 001	RCT	1/6/2015	West	WL-3 0-2' bgs
010615 002	RCT	1/6/2015	West	WL-3 2-4' bgs
010615 003	RCT	1/6/2015	West	WL-3 4-5' bgs
010615 004	RCT	1/6/2015	West	WL-3 5-10' bgs
010615 005	RCT	1/6/2015	West	WL-3 10-15' bgs
010615 006	RCT	1/6/2015	South	WL-3 location
010615 007	RCT	1/6/2015	South	WL-4 0-2' bgs
010615 008	RCT	1/6/2015	South	WL-4 2-4' bgs
010615 009	RCT	1/6/2015	South	WL-4 4-12.5' bgs
010615 010	RCT	1/6/2015	North	WL-4 location
010615 011	RCT	1/6/2015	North	WL-5 location
010615 012	RCT	1/6/2015	West	WL-5 0-2' bgs
010615 012A	RCT	1/6/2015	West	WL-5 2-13' bgs

East White Lake Property
Vermilion Parish, LA

Photo ID	Photographer	Date	Direction	Description
010615 013	RCT	1/6/2015	West	WL-6 0-2' bgs
010615 014	RCT	1/6/2015	South	WL-6 2-4' bgs
010615 015	RCT	1/6/2015	South	WL-6 4-6' bgs
010615 016	RCT	1/6/2015	South	WL-6 6-8' bgs
010615 017	RCT	1/6/2015	South	WL-6 8-10' bgs
010615 018	RCT	1/6/2015	South	WL-6 10-13' bgs
010615 019	RCT	1/6/2015	South	WL-6 locatin with well
010615 020	RCT	1/6/2015	West	WL-7 0-2' bgs
010615 021	RCT	1/6/2015	West	WL-7 location
010615 022	RCT	1/6/2015	West	WL-7 2-4' bgs
010615 023	RCT	1/6/2015	West	WL-7 4-6' bgs
010615 024	RCT	1/6/2015	West	WL-7 6-8' bgs
010715 001	RCT	1/7/2015	North	WL-8 location
010715 002	RCT	1/7/2015	Northeast	WL-8 0-2' bgs
010715 003	RCT	1/7/2015	Northeast	WL-8 2-4' bgs
010715 004	RCT	1/7/2015	Northeast	WL-8 4-6' bgs
010715 005	RCT	1/7/2015	Northeast	WL-8 6-8' bgs



010515 001



010515 002



010515 003



010515 004



010515 005



010515 006



010515 007



010515 008



010515 009



010515 010



010515 011



010515 012



010515 013



010515 014



010515 015



010615 001



010615 002



010615 003



010615 004



010615 005



010615 006



010615 007



010615 008



010615 009



010615 010



010615 011



010615 012



010615 012A



010615 013



010615 014



010615 015



010615 016



010615 017



010615 018



010615 019



010615 020



010615 021



010615 022



010615 023



010615 024



010715 001



010715 002



010715 003



010715 004



010715 005