Westlake US 2 Daily Report Date Reported: 3/14/2023

### **Pressure Data:**

### 3/13/2023 @ 6PM

7B Tubing Press = 79.9 psig
7B Annulus Press = 444.7 psig
7B Brine Injection Rate = 239.6 GPM
6X Tubing Press = 187.1 psig
6X Annulus Press = 189.7 psig

Only daylight oil withdrawal ops from PPG 7B to PPG 20 (as needed).
Oil Injection into PPG 20:

3/13 = 0 bblsTotal = 6,596 bbls

# 3/14/2023 @ 4AM

7B Tubing Press = 85.7 psig

Downhole Pressure in 7B Tubing = 1440 psig

7B Annulus Press = 451.2 psig

7B Brine Injection Rate = 238.6 GPM

6X Tubing Press = 187.3 psig

6X Annulus Press = 189.7 psig

## **Site Observations:**

-No new observations or major changes.

# **Operational Notes:**

- -Transporters for Buckhead midstream will be on site to haul 6,000 of #7b oil that has been stored temporarily in #20.
- -#7 wellhead repair and sonar planned for Wed/Thur.
- -Added new barricade tape at #1 location (E of #22)



# Sulphur Field Observation Daily Report (Nightshift)

Yellowrock Fee 7 air testing  O2  LEL  H2s	Well head 7A air testing O2 LEL	Well Pad 22 air testing (CL-1) O2 LEL H2s	6x Tubing Pressure 6x Annulus Pressure	7b Tubing Pressure 7b Annulus Pressure 7b Injection Rate
e 7 air testir O2 LEL	air testing O2 LEL	r testing (CL O2 LEL H2s	sure	sure ssure
00/0	0 0 0	0 0 0.1¢	187.0	9.84h
(Circle One)	(Circle One)	(Circle One)	1.781	7.76.6 L. SATH 60.00
More intense	More Intense	More Intense	1897.2	L.8.E.C. 10.E.8 0.E.8
Less Intense	Less intense	Less intense	187,2 187,2 189,7 189,7	1,185°E
No Bubbles	No Bubbles	No Bubbles	187,2	9pm 83.5 450.6
No change	No change	No change	187.2	4.86e 2.64h 2.48
0000	0 0	0 0	187,3	8.987 4.02h 7.18 1.18
			187.3	12am 85/1 45/2/
			187.3	138,3 4,034 1,788
			187.3	238,3 451,1 238,3
			187, 3	3am 451,4 451,5
00 8	00	008	187.3	4ar n 85.7 451,2 338:6

**Sulphur Field Observation** Daily Report (Dayshift)

**Bubble Sites** 

8am 2pm

Well Pad 22 air testing (CL-1)

02	
LEI	

H2s

20.9	20.9
1	٥
1.0	6.0

(Circle One) More Intense Less Intense No change


Wellhead 7A air testing

02	20.8	20,5
	()	

LEL	0	0	
H2s	0.0	0.0	

(Circle One) No Bubbles More Intense Less Intense/ No change

Yellowrock Fee 7 air testing



(Circle One) Less Intense No Bubbles More Intense No change

#4 Pond air testing #1

O2	20.9	20.9
LEL	0	0
H2s	0.0	0.0

Less Intense (Circle One) More Intense No Bubbles No change

O2	20.9	20.9	
LEL	0	0	
H2s	0.1	0.0	


#4 Pond air testing #2

#7b wellhead testing

O2	20.8	20.9
LEL	0	0
H2s	0.0	0.0

(Circle One) More Intense Less Intense No Bubbles No change

(Circle One) More Intense Less Intense No Bubbles No change



Less Intense No Bubbles (Circle One) More Intense No change CL-9 20.9 0 02 LEL H2s (Circle One) No Bubbles No change More Intense Less Intense CL-9 20.9 02 0 LEL H2s New Observation, intensity Doneide Tape near middle pond. changes, or comments? thigh winds checked Big Pond from BANK. K.L. Perile Candon Signature: