Westlake US 2 Daily Report Date Reported: 8/13/2023

Pressure Data:

8/12/2023 @ 6PM

7B Tubing Press = 96.9 psig
7B Annulus Press = 450.1 psig
Downhole Pressure in 7B Tubing = 1437 psig
7B Brine Injection Rate = 284.1 GPM
6X Annulus Press = 190.8 psig
PPG 2 Tubing Pressure = 220.0 psig
PPG 2 Annulus Press = 741.6 psig

8/13/2023 @ 4AM

7B Tubing Press = 96.4 psig
7B Annulus Press = 450.4 psig
Downhole Pressure in 7B Tubing = 1438 psig
7B Brine Injection Rate = 254.2 GPM
6X Annulus Press = 191.0 psig
PPG 2 Tubing Pressure = 220.4 psig
PPG 2 Annulus Press = 744.7 psig

Site Observations:

-none

Operational Notes:

- -Brine injected into #7 is coming from the Starks dome
- -Injection pump issues resolved
- -Constant injection rate test started 8-13 @ 251 GPM. Plan is stop test at tubing pressure of 30 psi.




			0	ansritaM
P.OS.			20.8	zo
7)	ytisnetni ni egnena	More Intense Less Intense	(Sircle One)	Site 10 (Yellowrock #7)
	on - Briliddu8			
				PID (VOC)
			Ω	SZH
0			0	SO - - - - -
P.05			8.02	stič flaW bagguld AT
	on - 3n lddug the Bubbles on Intensity	More intense	(anO ələriə)	
			0	(DOV) OIA
				25H
			0	
F.05			8.02	20 (And 774 (D 7) 7 20C)
	on - gnibdud selddud oM	More Intense Less Intense	(Sircle One)	Site 1 (E of #22 BW)
			RAIL TO THE	
				S Annulus Pressure
L'hhl			9.1hL	
1-:027			0.027	2 Tubing Pressure
H-052			0.022	
	8.0018.001	0.191 8.091	8.0P1 T.0P1 0.0SS	6x Pressure
0.191 9.091 9.091 9.091 9.091		0.191 8.091	8.0p1 T.0p1	
0161 6061 6061 6061 6061 6061 8061 2082h1 2082h1 2082h1 2082h1	8.001 8.001 Ep8EHI Ep8EHI	0.191 8.091 298841 8.091	8.001 T.001 5p/1841 Ep/1841	91uzza14 xd
0161 6061 6061 6061 6061 6061		0.191 8.091 2985H1 5985H1 2.172 T.PTS	8.0p1 T.0p1	Ab Injection Rate Gauge The succession of the
0161 6:061 6:061 6:061 6:061 6:061 29/85HI 59/85HI 59/	8:012 L-812	5688HI 5688HI 512 L-62	8.001 T.001 5p/1841 Ep/1841 1.485 E.085	agueS alodnwod dT
0161 6:061 6:061 6:061 6:061 6:061 2/85h1 2/85h1 2/85h1 2/85h1 2/85h1 2/85h 2: hSZ Z 2SZ 8:65Z 6:20Z S:50Z 8:80Z h:05h h:05h 9:05h L:05h 9:05h h:05h	8:0LZ L-8LZ h-05h 1:05h	5688HI 5688HI 5-112 L-612 2-09h 2-09h	8.0b1 L.0b1 5/25h1 5/25h1 1.68Z 5.08Z 1.0Sh L.bhh	Ab Injection Rate Gauge The succession of the
0161 6:061 6:061 6:061 6:061 6:061 29/85HI 59/85HI 59/	8:012 L-812	5688HI 5688HI 512 L-62	8.0b1 L.0b1 5b/28h1 5b/28h1 1.68Z 5.08Z 1.0Sh L.bhh	Th Annulus Pressure Th Injection Rate Th Downhole Gauge


Sulphur Field Observation Daily Report (Nightshift)

Sulphur Field Observation Daily Report (Dayshift)

				ī
(Circle One)	More Intense	Lass Intense	No Bubbles	Bubbling - no
(circle Offe)	Wore interise	less intense	No Bubbles	change in intensity
	Morning	Afternoon		
!	abig	21.0		
	0	0		
	0.0	0.0	7	
	0.0	00		
· · · · · · · · · · · · · · · · · · ·		0.0		
(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - no change in intensity
72	Morning	Afternoon		
2	21.0	21.0		
	0	0		
,	0.0	10.0		
	110	0.0	1	
		0.0	+	
(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - no change in intensity
	Morning	Afternoon		
	04.0	21.0	1	
	_ 0	0	j	
H2s		0.0		
1	0.0	0.0		
,				
(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - no change in intensity
		A		
2	41.1	21.0		
•	0	0		
6	0.0	0.0		
)	0.0	0.0		
(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - ne
	Morning	Afternoon	- (intensity
2	210	21.0		
Methane H2s PID (VOC)		0		
		0.0		
		A.D		
		0.0		
×				
(Circle One)	More Intense	Less Intense Afternoon	No Bubbles	Bubbling - n change in intensity
	(Circle One) (Circle One) (Circle One)	Morning AD 9 Corcle One) More Intense Morning AD 0 Corcle One) More Intense	Morning Afternoon ADIA 21.0 O O O O O O O O O O O O O O O O O O O	Morning Afternoon Alternoon Altern

Site 7 (Central Lake)	(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - no change in intensity	
		Morning	Afternoon		1	
	02	21.1	21.0			
Metha	ne	0	0			
ı	12s	0.0	0.0			
PID (VO	oc)	0.0	0.0			





#26 Bubble site (Crystal Lake Blg Pond)	(Circle One)	More Intense	Less Intense	No Bubbles	Bubbling - no change in intensity
		Morning	Afternoon		
02		21,	21.0		
Methane		0	0		
H2s		0,0	0.0		
PID (VOC)		0.0	0.0		

#7 Well Pad Site General Housekeeping

Check Berms for leaks or oil/brine
Check hoses at each connection from rental pump to piping tie-in
Check cellar for oil
Check Wellinead for leaks

New Observation or comments?

Cell #1 - 74 Sull Cell #2-3/4 Full Pump - Sull

Signature: