

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date:	Wednesday, January 2	25, 2023 Time of Arriv	al: 10:50 AM	Time of Departure	:: 1:37 PM
Inspector N	ame(s): Seth Hender	rson, Katie Robinson, Meliss	a Ashour, Jeff Miller		
Other perso	onnel on site: J	osh Bradley (Westlake), Sco	t Hines (ERM), Randy (Westl	ake), Kevin (Westlake)	
Weather Co	onditions (Temp/Wind S	Speed/Direction, etc.):	West wind. 10 mph. 48 de	egrees	

Any planned work for today: Witness sampling by ERM

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-2	CL-3	CL-4	Yellow Rock	Yellow Rock	Flowlines
(location description):				(near BW-22, west						
				side of Central	(east side of Central	(Central Lake	(Central Lake			(all brine and oil
				Lake)	Lake)	bubbling site)	bubbling site)	S-4 SWD	S-7 SWD	flowlines)
General Comments:		Still slight bubbling	Oil is now piped from 7B casing to BW 20. 1.5 bbls/min	area. Westlake previously excavated this area deeper	filled in. Josh suggested the orange staining near pond			SN 109963	SN 110159	Salt buildup on pipe fitting near S-7.
Photos taken? (save to F: drive)	No	Yes	Yes	Yes	Yes	N/A	N/A	No	No	
Tubing Pressure (if applicable)	184.1	N/A	97	N/A	N/A	N/A	N/A	0	128	
Casing Pressure (if applicable)	184.5	N/A	450	N/A	N/A	N/A	N/A	N/A	30	
Bubbling?	No	Yes	No	Yes	No	N/A	N/A	No	No	
Sheen?	No	No	No	Yes	Yes	N/A	N/A	No	No	
Oil?	No	No	No	Yes	No	N/A	N/A	No	No	
Odor?	No	Yes	Yes	Yes	Yes	N/A	N/A	No	No	
Any new remedial work?	No	No	No	Yes. See above.	Yes. See above.	N/A	N/A	No	No	
Any impact to vegetation?	No	No	No	Nothing new	Yes	N/A	N/A	No	No	
Any impact to wildlife?	No	No	No	Nothing new	No	N/A	N/A	No	No	

