Inspection Form   OFFICE OF CONSERVATION   Inspection & MINING DIVISION   Inspection Support   Inspection Support   Inspection Support   Inspector Name(s):   Keith Goureaux   Other personnel on site:   Watter Conditions (Temp/Wind Speed/Direction, etc.):   Al Bagrees, Cloudy, Winds SSE at 6 mpl															
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	(near BW-22, west	CL-2 (east side of Centra Lake)	CL-3 I (Central Lake bubbling site)	CL-4 (Central Lake bubbling site)	Yellow Rock Disposal Wells	Flowlines (all brine and oil flowlines)						
General Comments:			Brine Injection moved from 7B to #20	Absorbent boom has been placed on the north side of bubbling to contain oil	Remedial dirt work to seal off pond near LGS #1 P&A well	Not Inspected	Not Inspected							SN 110159 45 psi SITP SN 109963 0 psi SITP SN 195916 15 psi SITP	
Photos taken? (save to F: drive)	No	Yes	No	Yes	Yes	N/A	N/A	No							
Tubing Pressure (if applicable)	*200	N/A	86.2	N/A	N/A	N/A	N/A	125	105	Shut In	100	Shut In	Shut In		
Casing Pressure (if applicable)	*180	N/A	438.5	N/A	N/A	N/A	N/A	125	105	Shut In	Shut In	70	Shut In		
Bubbling?	No	Yes	No	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Sheen?	No	No	No	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Oil?	No	No	No	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Odor?	No	No	No	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Any new remedial work?	No	No	No	Sorbent Boom	Dirt work	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Any impact to vegetation?	No	No	No	Nothing New	None Visible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Any impact to wildlife?	No	No	No	No	None Visible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
NOTES	*Pressures from analog gauges														