INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, January 30, 2023 Time of Arrival: appox. 9 am Time of Departure: appox. 1 pm Inspector Name(s): Billy Carnes, Schirmer Durio Other personnel on site: N/A										
Weather Conditions (Temp/Wind Speed/E		Around 59* N 6 mp	-					SA 50	RW No. 4	
Any planned work for today: Sample	new bubbling sites & re	egular Site Inspection							A Constant And A Cons	
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	<b>CL-2</b> (east side of Central Lake)	CL-3 (Central Lake bubbling site)	CL-4 (Central Lake bubbling site)	CL-5 (Central Lake bubbling site)		Flowlines (all brine and oil flowlines)
General Comments:	No changes around Wellhead or Pad	No Changes	Operator @ time of Inspection was injecting 246 gpm of Brine water. No changes around Wellhead or Pad	No Changes	No Changes	No Changes	No Changes	New Bubbling site Lat 30*15'15.033 Log -93*24'45.5"		
Photos taken? (save to F: drive)	no	no	no	no	no	no	no	yes		
Tubing Pressure (if applicable)	185		54							
Casing Pressure (if applicable)	184		196							
Bubbling?	no	yes	no	Yes	yes	yes	yes	yes		
Sheen?	none	none	none	yes	none	none	none	none		
Oil?	no	no	no	yes Small amount	no	no	no	none		
Odor?	no	no	no	yes	no	no	no	none		
Any new remedial work?	none	none	none	none	none	none	none	none		
Any impact to vegetation?	none	none	none	none	none	none	none	none		
Any impact to wildlife?	none	none	none	none	none	none	none	none		