OF CONSERVATO	

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET **BATON ROUGE, LA 70802**

Location: Sulphur Mines Dom	۱e
-----------------------------	----

Date: Monday, February 6, 2023 Time of Arrival:

9:00 AM

Time of Departure:

1:00pm

Other personnel on site: Randy Broussard

Inspector Name(s): Billy Carnes

Other personnel on site:

Weather Conditions (Temp/Wind Speed/Direction, etc.): Clear skies 67* SSE 12

Any planned work for today: Inspected around Site for any new bubbling or other new developments

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-2	CL-3	CL-4	Cavern Well #020	Flowlines
(location description):				(near BW-22, west side of Central Lake)					
							(Central Lake		(all brine and oil
						bubbling site)	bubbling site)		flowlines)
General Comments:	No Changes	No Changes	Operator not flowing Oil out of Cavern today	No changes	Not inspected	Not inspected	Not inspected	Operator had set up this Cavern to receive the Oil from Cavern Well #007B, Operator has shut down the Oil or flow from Cavern Well #007B and started Brine Mining Cavern again.	
Photos taken? (save to F: drive)	Νο	no	no	no				no	
Tubing Pressure (if applicable)	187 psi		84 psi					23 Brine water flow	
Casing Pressure (if applicable)	188 psi [oil pad]		426 psi					621 Water inj. Psi	
Bubbling?	no	yes	no	yes				no	
Sheen?	no	no	no	yes				no	
Dil?	no	no	no	yes				no	
Odor?	no	no	no	yes				no	
Any new remedial work?	no	no	no	Added an extra Oil boom				Removed Oil & Water seperator	
Any impact to vegetation?	none	none	none	no				none	
Any impact to wildlife?	none	none	none	none				none	

