Ç,	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802																
Location: Sulphur Mines Dome Date: Friday, February 10, 2023 Time of Arrival: 10:35:00 AM Inspector Name(s): Kelth Goutreaux					Time of Departure: 1:00:00 PM Other personnel on site:												
		CO Deserves Claude	China Malada Miblior at	C analy	Oui	er personner on site								TATALAN AND	1	1	
Weather Conditions (Temp/Wind Speed/Dir			/ Skies, Winds NNW at									1	A A MA	J'arman			
Any planned work for today: Inspections of locations designated on spreadsheet. Bubbling locations that are only visible by boat will not be inspected.																	
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	Cavern Well #20	CL-1	CL-2	CL-3	CL-4	Yellow Rock	Flowlines							
(location description):				Oil Pad Injection	(near BW-22, west side of Central Lake)	(east side of Central Lake)	(Central Lake bubbling site)	(Central Lake bubbling site)	SN 209459	SN 210185	SN 209445	SN 159213	SN 189416	SN 207343	Disposal Wells	(all brine and oil flowlines)	
General Comments: Changes to entry access beyond sign in/sign out, now requiring work permit with general form of activity to be filed, FRC's, Steel Toes, Safety glasses, H25 Monitors. Workover rig moved in on North side of Caverns for Westlake Chemical, unknown work permit being performed.		Locked Gate	Locked Gate	Stopped Injection	More Absorbent boom addeddue to weather on the north side of bubbling to contain oil & sheen		Not Inspected	Not Inspected									
NOTES:	No	No	No	No	No	No	N/A	N/A	No	1							
Tubing Pressure (if applicable)	*200	N/A	90	N/A	N/A	N/A	N/A	N/A	50	200	0	75	84	Shut In	N/A		
Casing Pressure (if applicable)	*185	N/A	448	N/A	N/A	N/A	N/A	N/A	50	135	30	105	70	Shut In	N/A		
Bubbling?	No	Same	No	N/A	Same	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Sheen?	No	No	No	N/A	Same	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Oil?	No	No	No	N/A	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Odor?	No	No	No	N/A	Yes	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Any new remedial work?	No	No	No	N/A	additional Boom	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Any impact to vegetation?	No	No	No	N/A	Nothing New	None Visible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
Any impact to wildlife?	No	No	No	N/A	No	None Visible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
	*Pressures from analog gauges		248 gal/min														
NOTES:			Injecting	Stopped Injection													