	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802									
Location: Sulphur Mines Dome Date: Monday, February 13, 2023 Time of Arrival: 9:00:00 AM Time of Departure: 2:20:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard Weather Conditions (Temp/Wind Speed/Direction, etc.): Clear 67* SW9 mph Any planned work for today: Inspect bubbling sites (new & old) Cavern well pressure's, and Inspect Yellow Rocks shut-in Injection Wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-2 (east side of Central Lake)	CL-3 (Central Lake bubbling site)	CL-4 (Central Lake bubbling site)			Flowlines (all brine and oil flowlines)
			237.6 gpm/ small bubbling train along side the Well casing [new]	The boolding in this hole seems to be less intensive today. Also Operator replace the absorbent boom with new absorbent boom by the bubbling area, I had requested my contact Randy/Westlake to put clean absorbent	no changes	no access	no access	New bubbling sites Corrdinates N30*15'12.14 W92*24'41.25" N30*15'11.49 W93*24'42.94 N30*15'11.84 W93*24'44.55"		
Photo's taken	no	no	no	no	no			no		
Tubing Pressure (if applicable)	188.6	no	92.9							
Casing Pressure (if applicable)	189.8	no	451							
Bubbling?	no	yes	yes	yes	no			yes		
Sheen?	no	no	no	yes	no			no		
Oil?	no	no	no	yes	no			no		
Odor?	no	no	no	very little	no			no		
Any new remedial work?	none	none	none	yes	none			none		
Any impact to vegetation?	none	none	none	none	none			none		
Any impact to wildlife?	no	no	no	no	no			no		