AND TO THE OTHER	INSPECTION FORM							BW No 21	Summer of the	
OFFICE OF CONSERVATION									SP DEC	
INJECTION & MINING DIVISION										B.W. No. 23 Relive AN Relive AN
617 NORTH 3RD STREET										P23561
BATON ROUGE, LA 70802										
Location: Sulphur Mines Dome										
Date: Friday, February 17, 2023 Time of Arrival: 12:00:00 AM Time of Departure: 12:00:00 AM									Marchan State Stat	
Inspector Name(s): Schirmer Durio Other personnel on site:										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 42 Degrees / Clear Skies / 10 mph N Winds										
Any planned work for today:										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-2	CL-3	CL-4	CL-5	Pig Clean Out	Yellow Rock Wells
(location description):				side of Central Lake)	(east side of Central Lake)	(Central Lake bubbling site)	(Central Lake bubbling site)	(Central Lake bubbling site)		
General Comments:										
				Sorbent booms						SN 110159 (SWD) tbg. 58 csg. 0 / SN
			Pumping unit on	surrounding bubbling. 1						109963 (SWD) tbg. 2 csg. 0 / SN
		Minor bubbling in	location. 242 GPM		Could not observe		Could not observe	Could not observe		2099349 tbg. 58
	#NAME?	cellar (2 spots)	pump rate	observed.	bubbling	bubbling	bubbling	bubbling	Location Clean	csg 68
Photos taken? (save to F: drive) Tubing Pressure (if applicable)	no	no N/A	no	no N/A						
Casing Pressure (if applicable)		N/A		N/A						
Bubbling?	no	yes	no	yes						
Sheen?	no	no	no	yes						
Oil?	no	no	no	slight residual						
Odor?	no	no	no	Unable to detect						
Any new remedial work?	no	no	no	booms in place						
Any impact to vegetation?	no	no	no	minor, no change						
Any impact to wildlife?	no	no	no	no						