INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, February 20, 2023 Time Of Arrival 9:20:00 AM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard & Turner contract Weather Conditions (Temp/Wind Speed/Direction, etc.): Cloudy 71* SW 16 mph Any planned work for today: Inspect Cavern Wells, Bubbling sites & some Yellow Rock Wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-2 (east side of Central Lake)	CL-3 (Central Lake bubbling site)	CL-4 (Central Lake bubbling site)	CL-5 (Central Lake bubbling site)	CENTRAL LAKE OPEN WATER BUBBLING SITES	Yellow rock Wells #1012 s/n 210185 260psi #1012 s/n 209459
General Comments:		No Changes	Surface Casing	No changes on the bubbling or on the Oil sheen	There is nothing Happening at this location @ this spot.	NO ACCESS	NO ACCESS	NO ACCESS	Found 1 new bubbling site N30* 15' 14.98" W93* 24' 46.5 The other open water bubbling sites seem to be less Intense today	
Photos taken? (save to F: drive)	NO	NO	Westlake took Pic.	NO					Westlake took Video	
Tubing Pressure (if applicable)	188.7	-	77psi	-					-	
Casing Pressure (if applicable)	190.2	-	441psi	-					-	
Bubbling?	NO	YES	YES	YES			_		YES	
Sheen?	NO	NO	NO	YES			_		NO	
Oil?	NO	NO	NO	LITTLE					NO	
Odor?	NO	NO	NO	LITTLE					NO	
Any new remedial work?	NO	NO	NONE	NO					NO	
Any impact to vegetation?	NO	NO	NO	NONE					NONE	
Any impact to wildlife?	NO	NO	NO	NO					NO	