Location: Sulphur Mines Dome Date: Wednesday, February 22, 2023 Inspector Name(s): Schirmer Durio Weather Conditions (Temp/Wind Speed/Di Any planned work for today: Field surv	rection, etc.):	9:00:00 AM Winds 10-15 SE, Ov	INJE E	CTION & MI 617 NORTH ATON ROUG	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802	DN :00 AM				En
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-2 (east side of Central Lake)	CL-3 (Central Lake bubbling site)	CL-4 (Central Lake bubbling site)	CL-5 (Central Lake bubbling site)	CL-9 (Central Lake bubbling site)	Yellow Rock
General Comments:		minor bubbling at cellar	Pumping unit on location Pumping at 241 gpm	Slightly less oil observed. Still bubbling.		Could not observe bubbling		Could not observe bubbling	Could not observe bubbling	SN 110159 (SWD)tbg 60 csg o / SN 109963 (SWD) tbg 5 csg 0 / SN 2099349 tbg 48 csg 55
Photos taken? (save to F: drive)	no	no	no	no						no
Tubing Pressure (if applicable)	205	NA	87	NA						see above
Casing Pressure (if applicable)	185	NA	453	NA						see above
Bubbling?	no	yes	no	yes (1 spot)						no
Sheen?	no	no	no	Yes (minor)						no
Oil?	no	no	no	minor						no
Odor?	no	no	no	winds too high						no
Any new remedial work?	no	no	no	no						no
Any impact to vegetation?	no	no	no	nothing new						no
Any impact to wildlife?	no	no	no	no						no