

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Date: Wednesday, March 1, 2023

Inspector Name(s): Sarah Hitchcock

Location: Sulphur Mines Dome

Time of Departure: 1:15:00 PM Other personnel on site: J Bradley, D Jeeter, P Tucker

Weather Conditions (Temp/Wind Speed/Direction, etc.): 78 Degrees/Cloudy; Wind SSE at 19 mph

Any planned work for today: Inspect Bubbling Locations and Check Pressures

Time of Arrival: 11:15:00 AM

	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west	CL-2	CL-3	CL-4	CL-5	Yellow Rock Wells	Flowlines
(location description):				side of Central	(east side of Central	(Control Lako	(Central Lake	(Central Lake	Two SWDs and One	(all bring and oil
				Lake)		bubbling site)	bubbling site)	bubbling site)		flowlines)
				Lakej	Lakej	bubbillig site)	DUDDINg Site)	Dubbiling site)	FIGUUCCION	nowinies)
General Comments: Too windy to observe bubbling locations near bulkhead in Central Lake										
		The pad is dry, so if there is bubbling it		Oil present and contained by sorbent boom.	51/2				SN 110159 (SWD) tbg - 70, csg - 0; SN 109963 (SWD) tbg - 3, csg - 0; SN 209459 (Producer) tbg - 60,	
		cannot be seen.	Pumping 240 gpm	Bubbling the same.	N/A	No Access	No Access	No Access	csg - 55	
Photos taken? (save to F: drive)	No	No	No	No						
Tubing Pressure (if applicable)	189	N/A	89	N/A						
Casing Pressure (if applicable)	191	N/A	451	N/A						
Bubbling?	No	No	Yes	Yes						
Sheen?	No	No	No	Yes						
Oil?	No	No	No	Yes						
Odor?	No	No	No	No (Standing Upwind)						
Any new remedial work?	No	No	No	No						
Any impact to vegetation?	No	No	No	Nothing New						
Any impact to wildlife?	No	No	No	No						