

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, March 13, 2023 Time of Arrival: 9:30am Time of Departure: 12:00 PM

Inspector Name(s): William [billy] Carnes

Other personnel on site: Randy Broussard & other Westlake personal

Weather Conditions (Temp/Wind Speed/Direction, etc.): Party Cloudy 54* + NE 14 mph

Any planned work for today: Inspect Bubbling sites, Cavern Wells ans some of the Yellowrock Wells



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B		CL-2	CL-3	CL-4	CL-5	CL-9
(location description):				(near BW-22, west					
				side of Central	(east side of Central	1,	(Central Lake	(Central Lake	Bubblng under
				Lake)	Lake)	bubbling site)	bubbling site)	bubbling site)	cable tray
General Comments:									
			Line form Brine						
			pump to Wellhead						
			had a couple of			Central Lake			
		No Fluid on the Pad				Bubbling sites hard			
		so I can't tell how	leaks that have			to inspect because			Bubbling seems less
			salted closed.			of Brezzy			intense today in
		today.	239 gpm	No Change	N/A	Conditions			this area
Photos taken? (save to F: drive)	no	no	no						
Tubing Pressure (if applicable)	188		78						
Casing Pressure (if applicable)	190	ı	445						
Bubbling?	no		small bubbling						
Sheen?	no		no						
Oil?	no		no						
Odor?	none		no						
Any new remedial work?	no		none						
Any impact to vegetation?	none		no						
Any impact to wildlife?	no		none						