Location: Sulphur Mines Dome Date: Thursday, March 16, 2023 Inspector Name(s): Sarah Hitchcok	Time of Arrival:	12:0	INJE	CTION & MI 617 NORTH	NSERVATION NING DIVISIC 3RD STREET 5E, LA 70802					ETTER THE THE THE THE THE THE THE THE THE THE
Other personnel on site: J Bradley, K Lavergne, R Broussard, Lonquist Weather Conditions (Temp/Wind Speed/Direction, etc.): 71 Degrees, Winds SSE at 15 mph, Overcast Any planned work for today: Check pressures and inspect bubbling sites										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL 11-16 (east side of Central Lake)	Location 9 (Water location between PPG 2 and PPG 4)	CL-4 (Central Lake bubbling site)	CL-5 (Central Lake bubbling site)	Yellow Rock Wells Two SWDs and One Production	
General Comments: Lonquist is on site conducting sonar on 7B. The unregistered water well near the cabins was located, photographed, and GPS coordinates were obtained. (30.251844, -93.419108)		The pad is dry so if there is bubbling it can't be seen.	Inj Rate 216 gpm	Oil contained by sorbent boom	Too windy to observe****	Appears the same, but hard to observe all locations due to wind	No Access	No Access	SN 110159 (SWD) tbg - 85, csg - 0; SN 109963 (SWD) tbg - 5, csg - 0; SN 209459 (Producer) tbg - 50, csg - 55	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	187	N/A	100.2	N/A	N/A	N/A				
Casing Pressure (if applicable)	190	N/A	450.9	N/A	N/A	N/A				
Bubbling?	No	No	No Access to Cellar	Yes	****	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				