INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, March 23, 2023 Time of Arrival: 12:00 PM Time of Departure: 2:00 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, R Broussard, K Lavergne, Other Westlake Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 74 degrees, S Wind at 12 mph, Overcast

Any planned work for today: Check pressures and observe bubbling locations

Inspection locations: (location description):	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**CL 11-16** (east side of Central Lake)	**Location 9** (Water location between PPG 2 and PPG 4)	**CL-4** (Central Lake bubbling site)	**CL-5** (Central Lake bubbling site)	**Yellow Rock Wells** Two SWDs and One Production	**Flowlines** (all brine and oil flowlines)
General Comments:		The pad is dry so if there is bubbling it can't be seen.	Inj rate 231 gpm; Removing oil from 7B to PPG 20	New contruction fencing to replace barrier tape; Oil contained by sorbent boom	Only one small bubble location noted near the bulkhead	Only one small bubble location noted	No Access	No Access	**SN 110159** (SWD) tbg - 95, csg - 0; **SN 109963** (SWD) tbg - 5, csg - 0; **SN 209459** (Producer) tbg - 50, csg - 45	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	186.7	N/A	90.3	N/A	N/A	N/A				
Casing Pressure (if applicable)	189.9	N/A	457.1	N/A	N/A	N/A				
Bubbling?	No	No	Yes	Yes	Yes	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				