INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, March 20, 2023 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM Inspector Name(s): William (Billy) Carnes Other personnel on site: Randy Broussard & Tanner contractors Weather Conditions (Temp/Wind Speed/Direction, etc.): Clear - Sunny 44* - 46* E10 mph Any planned work for today: Inspect Cavern Wells & Bubbling sites & some Yellow Rock Wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-2	CL-3	CL-4	CL-5		Yellow Rock
nocation description.				side of Central	(east side of Central		(Central Lake	(Central Lake		
				Lake)	Lake)	bubbling site)	bubbling site)	bubbling site)	Central Lake	Swd Wells
Some of the Bubbling sites seem to be less intense than previous inspections.		Due to no fluid on P							In Central Lake in	
		& A pad area you can't tell if their's							general it is less intense bubbling	S-4 0 psi tubing
		still bubbling on							action & there is No	
		pad.	239 gpm						Oil or Odor	# 1012 50 psi tubing
Photos taken? (save to F: drive)				no						
Tubing Pressure (if applicable)	186		93 PSI							
Casing Pressure (if applicable)	189		459 PSI							
Bubbling?			YES	yes	none					
Sheen?			no	yes	none					
Oil?			no	yes	none					
Odor?			none	not really	none					
Any new remedial work?			no	no	none					
Any impact to vegetation?			no	none	none					
Any impact to wildlife?			no	no	none					