INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, March 27, 2023 Time of Arrival: 9:20am Time of Departure: 11:40am Inspector Name(s): William [Billy] Carnes Other personnel on site: Randy Broussard & Tanner personal Weather Conditions (Temp/Wind Speed/Direction, etc.): Cloudy 71* NE 9 to 10 mph Any planned work for today: Check some Cavern Well pressure's & some Yellowrock Well tubing pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-5 See map	site 9 & 19	CL-6,7,15,16,8,14 (Central Lake bubbling site)	CL-5 (Central Lake bubbling site)	Yellowrock Wells	Cavern #20
Road in the Boat today to check Bubbling site's in central Lake On Inspection I observed that some of the bubbling site's are less intense or not bubbling at all. But I notice 2 new small bubbling site's and the Westlake Representative will GPS & video the action.		No Fluid on wellpad so I can't tell if there is still bubbling on the P & A pad	233 gpm	Operator change Oil boom & placed a new Oil boom around bubbling site	Less intensive bubbling	bubbling has almost stopped @ time of inspection		Less intense then previous inspections	#1012 40 psi tubing # S-4 0 psi tubing S-7 92 psi tubing	No activity today
Photos taken? (save to F: drive)			no	no						
Tubing Pressure (if applicable)	186		94							
Casing Pressure (if applicable)	190		458							
Bubbling?			yes	yes						
Sheen? Oil?			no	yes						
Odor?			no	yes yes						
Any new remedial work?			none	no						
Any impact to vegetation?			no	none						
Any impact to wildlife?			none	no						