INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, April 3, 2023 Time of Arrival: 9:20 AM Time of Departure: 11:40 AM Inspector Name(s): William [Billy] Carnes Other personnel on site: Randy Broussard Weather Conditions (Temp/Wind Speed/Direction, etc.): Cloudy 76 deg. SSW 14 mph Any planned work for today: Check Cavern Wells pressure's, Bubbling site's and some of the Yellow Rock wells.										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	CL-9-11	CL-3 (Central Lake	CL-4 (Central Lake	CL-5 (Central Lake	Cavern Well 20	Yellowrock
				Lake)	UNDER PIPES	bubbling site)	bubbling site)	bubbling site)		Inspected 3 Wells
Operator has fixed leaking flange on on 7B well pump and has cleaned pad of Brine water leakage. Josh w/Westlake notified me this morning that Westlake was going to start installing the semi-permanent seismic monitors today. No changes in the Bubbling site's that I could see today, windy condititions curtail the boat ride to check the bubbling in Central Lake.		Could not see bubblings because Well Pad has no fluid.	237gpm		No Changes	N\A	N/A	N/A	No activitywith this Well during inspection	#1012 40psi tubing S-4 0psi tubing S-7 95psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	186		94							
Casing Pressure (if applicable)	189		458							
Bubbling?			yes, by casing	yes						
Sheen?			no	yes						
Oil?			no	yes						
Odor?			no	yes						
Any new remedial work?			no	no						
Any impact to vegetation?			no	none						
Any impact to wildlife?			no	no						