Location: Sulphur Mines Dome Date: Monday, April 10, 2023 Inspector Name(s): William (Billy) Carnes Other personnel on site: Randy Bro Weather Conditions (Temp/Wind Speed/Dird	INJE	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Time of Departure: 12:30 PM								
Any planned work for today: Check bubbling locations, some cavern Well Pressures & some of the Oil & Gas Operator Yellowrock wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Sites 9 & 19	CL-12,16,15,8 (Central Lake bubbling site)	Central Lake sites	Yellowrock Well S-4 swd	Yellowrock	
Had fluid on the 7A pad and was able to see the bubbling, also the bubbling on 7A pad looks to have not changed from previous inspections.										
		This Cavern Well is P & A	256 gpm of Brine being injected into cavern.	No changes from previous inspection on 4/3/2023	no changes from previous inspection on 4/3/2023	Bubbling was less intense from previous inspections	Didn't take a boat ride today	Operator has repaired this well & MIPT will be done @ a later date.	checked these wells tubing pressures #1012 30psi Tubing #S-4 0psi Tubing # S-7 95psi Tubing	
Photos taken? (save to F: drive)	no	no	no	no			, ,			
Tubing Pressure (if applicable)	189		81							
Casing Pressure (if applicable)	184		451							
Bubbling?	no	yes	yes	yes						
Sheen?	no	no	no	yes						
Oil?	no	no	no	yes						
Odor?	no	no	no	yes						
Any new remedial work?	no	no	no	no						
Any impact to vegetation?	no	no	no	no						
Any impact to wildlife?	no	no	no	no						