INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Thursday, April 20, 2023 Time of Arrival: 12:15 PM Time of Departure: 1:25 PM Inspector Name(s): Sarah Hitchcock Other personnel on site: Randy Broussard, Kevin Lavergne, Westlake Control Room Operator, Tanner Constuction Employees Weather Conditions (Temp/Wind Speed/Direction, etc.): 80 degrees, Wind SSE at 13 mph, Overcast Any planned work for today: Check pressures and observe bubbling locations										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	Location 9	Yellow Rock Wells	5		Flowlines
(location description):				(near BW-22, west side of Central	east side of Central	(Water location between PPG 2 and	Two SWDs and One			(all brine and oil
				Lake)	Lake)	PPG 4)	Production			flowlines)
General Comments:		Minimal water on the pad and no bubbling noted		Oil contained by sorbent boom; Bubbling more intense than on 4/6 visit	Only one small bubble location noted near the bulkhead	Bubbling not very intense. Appear to be the same as on 4/6.	SN 110159 (SWD) tbg -95, csg - 0; SN 109963 (SWD) tbg - 0, csg - 265; SN 209459 (Producer) tbg - 30, csg - 40			
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	180.5		97.2	-		N/A				
Casing Pressure (if applicable)		N/A	455.7			N/A				
Bubbling?		No	No	Yes	Yes	Yes				
Sheen?		No	No	Yes	No	No				
Oil?	-	No	No	Yes	No	No				
Odor?	-	No	No	Yes	No	No				
Any new remedial work?		No	No	New sorbent boom		No				
Any impact to vegetation?		No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				