INSPECTION FORM   OFFICE OF CONSERVATION   INSECTION & MINING DIVISION   Insector   Insector Sulphur Mines Dome   Insector Name(s): William [Billy] Carnes   Zether Conditions (Temp/Wind Speed/Direction, etc.): Cloudy 65* NE 12 mph   Any planned work for today: Check Cavern Well pressures, bubbling site's & some Yellowrock Wells										THE CONTRACT OF CO
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	<b>CL-1</b> (near BW-22, west side of Central	CL-9	CL-13 & 14	CL-15	CL-19	YELLOWROCK	
				Lake)	site map	site map	site map	site map	Wells	
Yellowrock is drilling a new production well by the Dome. Fee #1031 s/n 253998. Didn't take a boat ride because of the steady breeze and waves in central lake.			241 gpm small bubbling train along side of casing		very little bubbling	No bubbling I observed @ time of inspection.	small bubbling train	still a small bubbling train	S-4 s/n Opsi tubing 260psi casing S 7 95 tubing # 1012 30psi tubing	
Photos taken? (save to F: drive)				no	no		no	no	no	
Tubing Pressure (if applicable)	180		73							
Casing Pressure (if applicable)	184		449							
Bubbling?			yes	yes	yes		yes	no		
Sheen?			no	yes	no		no	no		
Oil?			no	yes	no		no	no		
Odor?			no	yes	no		no	no		
Any new remedial work?			no	no	no		no	no		
Any impact to vegetation?			no	no	no		no	no		
Any impact to wildlife?			no	no	no		no	no		