Location: Sulphur Mines Dome Date: Thursday, April 27, 2023 Inspector Name(s): Sarah Hitchcock Other personnel on site: J Bradley,	Time of Arrival: K Lavergne, Westlake	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802							
Weather Conditions (Temp/Wind Speed/Dir Any planned work for today: Check pre	ection, etc.): ssures and observe b		ny, West wind at 9 m	ph				RW No d Rytosa	
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL 11-16 (east side of Central Lake)	Location 9 (Water location between PPG 2 and PPG 4)	Yellow Rock Wells Two SWDs and One Production		Flowlines (all brine and oil flowlines)
General Comments:			Inj rate 247.8 gpm	Oil contained by sorbent boom	Only one small bubble location noted near the bulkhead	Bubbling not very intense. Heavy wind.	SN 110159 (SWD) tbg - 100, csg - 0; SN 109963 (SWD) tbg - 0, csg - 260; SN 209459 (Producer) tbg - 30, csg - 25		
Photos taken? (save to F: drive)	No	No	No	No	No	No			
Tubing Pressure (if applicable)	180.5	N/A	90.2	N/A	N/A	N/A			
Casing Pressure (if applicable)	184.3	N/A	449.5	N/A	N/A	N/A			
Bubbling?	No	Yes	Yes	Yes	Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			