INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, May 15, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:30 PM Inspector Name(s): William [Billy] Carnes Other personnel on site: Kevin LaVergne [Westlake] Collin Todd [Stan's Marsh Service] Tanner Industries contractors Weather Conditions (Temp/Wind Speed/Direction, etc.): party cloudy 76 deg. SE 4 mph Any planned work for today: Check Cavern Well pressures, Check bubbling site's, Check some Yellowrock Well pressures and ride Airboat in Central Lake, Crystal Lake & pond NE of										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-7,8,912,13,14, See Site Map	Cl-15,16,17,18,19 See Site Map	CL-3,6 & 24 (Central Lake bubbling site)	Cavern Well 2A	Yellowrock Well #1012	Yellowrock Wells
Rode in Airboat in pond on the NW side of Cavern 7B, Central Lake & Crystal Lake. Bubbling Site's look about the same as the prior Inspection on 5/8/2023							2220mig site)			
		Could not tell if theirs still bubbling on pad because pad is dry	259 gpm injection	On Inspection this site looked the same as on the 5/8/2023 inspection	Little to no Bubbling action	Same as Inspection on 5/8/2023	Same type of Bubbling as seen on the 5/8/2023 inspection			S-4 Opsi tubing 270 psi Casing S-7 100psi tubing
Photos taken? (save to F: drive)	no	no	no	no	no	no	no	no		
Tubing Pressure (if applicable)	181		93					213	20	
Casing Pressure (if applicable)	185		453					422	20	
Bubbling?			yes	yes	yes	yes	yes	no		
Sheen?			no	yes	no	no	no			
Oil?			no	yes	no	no	no			
Odor?			no	yes	no	no	no			
Any new remedial work?			no	no	no	no	no			
Any impact to vegetation?			no	no	no	no	no			
Any impact to wildlife?			no	no	no	no	no			