INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, May 22, 2023 Time of Arrival: 12:00 PM Time of Departure: 1:40 PM Inspector Name(s): Sarah Hitchcock Other personnel on site: J Bradley, K Lavergne, R Broussard, Control Room Personnel, ERM, Rig Crew at 6X Weather Conditions (Temp/Wind Speed/Direction, etc.): 79 Degrees, Sunny, Wind NW at 3 MPH Any planned work for today: Check pressures and observe bubbling locations										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	(near BW-22, west	CL 11-16	Location 9 (Water location	Yellow Rock Wells			Flowlines
					(east side of Central Lake)	PPG 4)	Production			(all brine and oil flowlines)
General Comments:	Gauges disconnected. Rig crew on location preparing for workover.	Pad is dry; no bubbling	Inj rate 263 gpm; Water level in cellar is low, so visible bubbling is minimal	Boom has recently	Only one small bubble location noted near the bulkhead	Same bubbling locations and intensity as noted during past inspections	SN 110159 (SWD) tbg - 95, csg - 0; SN 109963 (SWD) tbg - 0, csg - 280; SN 209459 (Producer) tbg - 30, csg - 25			
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	N/A	N/A	81.3	N/A	N/A	N/A				
Casing Pressure (if applicable)	N/A	N/A	440	N/A	N/A	N/A				
Bubbling?	No	No	Yes	Yes	Yes	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				