INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Wednesday, May 24, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:30 PM Inspector Name(s): William [Billy] Carnes Other personnel on site: Randy Broussard, Kevin LaVergne [Westlake] Rig Crew w/Lonquist co-man Weather Conditions (Temp/Wind Speed/Direction, etc.): Sunny 74* NE 4 mph Any planned work for today: Check Cavern wells & Bubbling site's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-9 & 19	CL-12,13,14,15,16	Cavern Well 2	Cavern Well 2A	Yellowrock wells	
(,				side of Central	see site bubbling	(Central Lake	(Central Lake	(Central Lake		
				Lake)	map	bubbling site)	bubbling site)	bubbling site)		
No boat ride today so boat accessable only bubbling site's not inspected today.										
		Pad dry so you can't			Visible bubbling on site 19 but site 9 was no bubbling action I observed @				S-4 Opsi tubing 275 psi casing S-7 95 psi tubing	
	Cavern Well	see the bubbling	268 gpm	done on 5/15/23	time of inspection.	observed			#1012 32 psi tubing	
Photos taken? (save to F: drive)			no	no	no		no	no		
Tubing Pressure (if applicable)			89				220	1.6		
Casing Pressure (if applicable)			439				543			
Bubbling?			yes	yes						
Sheen?			no	yes						
Oil?			no	yes						
Odor?			no	yes						
Any new remedial work?			no	no						
Any impact to vegetation?			no	no						
Any impact to wildlife?			no	no						