

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, June 1, 2023 Time of Arrival: 11:40 AM Time of Departure: 1:30 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, K Lavergne, R Broussard, Control Room Personnel, Westlake Techs, Lonquist, Triad

Weather Conditions (Temp/Wind Speed/Direction, etc.): 87 Degrees, Sunny, Wind ENE at 5 mph

Any planned work for today: Check pressures and observe bubbling locations



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B		CL 11-16		Yellow Rock Wells		Flowlines
(location description):				(near BW-22, west		(Water location			
				side of Central	(east side of Central	between PPG 2 and	Two SWDs and One		(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
General Comments:									
	Gauges disconnected; Running wireline	Pad is dry; no bubbling	Inj rate 276.5 gpm; Water level in cellar is low, so visible bubbling is minimal	Oil contained by	Only one small bubble location noted near the bulkhead	intensity (minor intensity) as noted during past	SN 110159 (SWD) tbg -95, csg -0; SN 109963 (SWD) tbg - 0, csg -280; SN 209459 (Producer) tbg -30, csg -25		
Photos taken? (save to F: drive)	No	No		No	No	No	10g 30, 63g 23		
Tubing Pressure (if applicable)	0	N/A			N/A	N/A			
Casing Pressure (if applicable)	0	N/A	441.8		N/A	N/A			
Bubbling?	No	No			Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			