INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802										eren Herrie Heri
Location: Sulphur Mines Dome Date: Monday, June 5, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:30 PM Inspector Name(s): William [Billy] Carnes Other personnel on site: Randy Broussard [Westlake] Weather Conditions (Temp/Wind Speed/Direction, etc.): 72* to 79* Partly cloudy NE 3 mph Any planned work for today: Ride in Airboat to inspect bubbling site's in Central Lake & Crystal Lake, Ck some Cavern Well pressures, Ck some Yellowrock Tubing well pressures)										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2B	CL 5,17,18,21,22,2 (Central Lake bubbling site)	2 CL 3,6 (Central Lake bubbling site)	CL 7,8,13,14,15.16 [Central Lake bubbling sites]	CL 22 [Central Lake bubbling sites]
Rode in Airboat to check bubbling site's in Central Lake & most bubbling site's look the same as last time that I rode in Airboat. In Crystal Lake didn't see any bubbling site's or indication of any issue's or problems. Workover Rig was still set up on Cavern #20, but some hands were working on Cavern #21 to get site ready for Workover Rig.		No fluid on pad so the bubbling can't be seen	Operator pumping 243 gpm into Cavern	Site look the same as prior inpections			About the same as last Inspection	Looked the same as last boat ride	On Inspection I notice NO bubbling at these sites	No changes since last inspection
Photos taken? (save to F: drive)				no			no	no	no	no
Tubing Pressure (if applicable)	204		68		231	1.2				
Casing Pressure (if applicable)	297		433		596					
Bubbling? Sheen?			Fluid below bubblin	1			yes no	yes no		yes no
Oil?				yes yes			no	no		no
Odor?				yes			no	no		no
Any new remedial work?	1			no			no	no		no
Any impact to vegetation?				no			no	no		no
Any impact to wildlife?				no			no	no		no