

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

Date: Thursday, June 8, 2023 Time of Arrival: 11:50 AM Time of Departure: 1:05 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, Control Room Personnel, Westlake Techs; Triad, Rig Crew

Weather Conditions (Temp/Wind Speed/Direction, etc.): 87 Degrees, Sunny, Wind W at 1 mph

Any planned work for today: Check pressures and observe bubbling locations

Inspection locations:	Cavern 6X	Cavern Well 7A		CL-1	CL 11-16	Location 9	Yellow Rock Wells		Flowlines
(location description):				(near BW-22, west		(Water location			
				side of Central	T, T	between PPG 2 and			(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
General Comments: Workover rig on BW 21		Pad is dry; no bubbling	Inj rate 281.6 gpm; Water level in cellar is low, so no		Only one small bubble location noted near the bulkhead	noted on water and reported to J	- 95, csg - 0; SN 109963 (SWD) tbg - 0, csg - 285; SN		
Photos taken? (save to F: drive)	No	No	No	No	No	Yes			
Tubing Pressure (if applicable)	175.4	N/A	74.3	N/A	N/A	N/A			
Casing Pressure (if applicable)	174.3	N/A	436.9	N/A	N/A	N/A			
Bubbling?	No	No	No	Yes	Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	No	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			